

Michael R. Pence Governor

Jerome M. Adams, MD, MPH State Health Commissioner

DATE:

October 14, 2015

TO:

All Local Health Departments

Attp: Chief Food Inspection Officer

FROM:

Laurie Kidwell, RRT Supervisor

Food Protection Program

SUBJECT:

Cook Medical – RECALL [Medical Device]

EXPANDED RECALL

AFFECTED

PRODUCT:

Beacon® Tip Angiographic Catheters

SUMMARY:

Unclassified Recall; The recall has been initiated because the Beacon Tip Angiographic Catheters have been found to exhibit tip splitting or separation, which has resulted in 42 Medical Device Reports. Tip

splitting has the potential to lead to loss of device function.

This recall includes all lots of these select sizes of the Beacon® Tip Angiographic Catheters. This recall is an expansion of the voluntary lot-specific recall issued on July 2, 2015. The products include specific versions of the Torcon NB® Advantage Beacon®Tip Catheters (catalog prefix HNBR4.0, HNBR4.1 and only HNBR5.0 with the RUC suffix), Royal Flush® Plus Beacon®Tip High-Flow Catheters (catalog prefix HNR4.0), and Slip-Cath® Beacon® Tip Hydrophilic Catheters (catalog prefix SCBR4.0, SCBR4.1, and only SCBR5.0 with the RUC suffix), and Shuttle®Select Slip-Cath® catheters (catalog prefix SCBR4.5). Below is a list of product catalog numbers.

The recalled products have been distributed nationwide.

SUGGESTED

ACTION:

For consumer inquiry only. Consumers with questions may contact Cook Medical Customer Relations at 1-800-457-4500 or 1-812-339- 2235, Monday through Friday, between 7:30 a.m. and 5:00 p.m. Eastern time or by email at CustomerRelationsNA@cookmedical.com.

Recall -- Firm Press Release

FDA posts press releases and other notices of recalls and market withdrawals from the firms involved as a service to consumers, the media, and other interested parties. FDA does not endorse either the product or the company.

For Immediate Release

October 9, 2015



Consumers

Cook Medical Customer Relations CustomerRelationsNA@cookmedical.com 1-800-457-4500 or 1-812-339- 2235

Media

Marsha Lovejoy, Global Manager, Corporate Content Strategy marsha.lovejoy@cookmedical.com 812.339.2235 ext. 2750 Firm Press Release

Original Recall

Purpose of the Press Release:

On October 7, 2015, Cook Medical initiated a voluntary recall for select sizes of Beacon® Tip Angiographic Catheters. This recall includes all lots of these select sizes of the Beacon® Tip Angiographic Catheters. This recall is an expansion of the voluntary lot-specific recall issued on July 2, 2015. The products include specific versions of the Torcon NB® Advantage Beacon®Tip Catheters (catalog prefix HNBR4.0, HNBR4.1 and only HNBR5.0 with the RUC suffix), Royal Flush® Plus Beacon®Tip High-Flow Catheters (catalog prefix HNR4.0), and Slip-Cath® Beacon® Tip Hydrophilic Catheters (catalog prefix SCBR4.0, SCBR4.1, and only SCBR5.0 with the RUC suffix), and Shuttle®Select Slip-Cath® catheters (catalog prefix SCBR4.5).

The Beacon Tip Angiographic Catheters have been found to exhibit tip splitting or separation, which has resulted in 42 Medical Device Reports. Tip splitting has the potential to lead to loss of device function. Tip separation may require medical intervention to retrieve a separated segment or, if not retrieved, has the potential to occlude blood flow to end organs.

The Beacon Tip Angiographic Catheters in this recall were distributed globally between September 2012 and September 2015. Product can be identified by the part number provided on the outer package product label. The part numbers for products subject to this recall are those with catalog number prefixes and suffixes listed in the initial paragraph above. All lots currently in distribution are affected.

Cook Medical has notified its customers and distributors by recall notification letters. The letters requested that all customers and distributors quarantine and discontinue use of all potentially affected units and return the affected product to the company as soon as possible for credit.

The FDA and other regulatory agencies around the world have been notified of this action.

Consumers with questions may contact Cook Medical Customer Relations at 1-800-457-4500 or 1-812-339-2235, Monday through Friday, between 7:30 a.m. and 5:00 p.m. Eastern time or by email at CustomerRelationsNA@cookmedical.com. Adverse reactions or quality problems experienced with the use

Adverse reactions or quality problems experienced with the use of this product may be reported to the FDA's MedWatch Adverse Event Reporting program either online, by regular mail or by fax. Complete and submit the report online at www.fda.gov/medwatch/report.htm or via regular mail or fax. Download the form at www.fda.gov/MedWatch/getforms.htm or call 1-800-332-1088 to request a reporting form, and then complete and return to the address on the preaddressed form, or submit by fax to 1-800-FDA-0178. Adverse events may also be reported to Cook Medical Customer Relations at 1-800-457-4500 or 1-812-339-2235, Monday through Friday, between 7:30 a.m. and 5:00 p.m. Eastern time or by email at CustomerRelationsNA@cookmedical.com.

Beacon® Tip Angiographic Catheters Recall Extension - Affected Lot Numbers Beacon® Tip Royal Flush® Plus High-Flow Catheter

Product Catalog Numbers

HNR4.0-35-100-P-10S-0, HNR4.0-35-100-P-10S-CFP, HNR4.0-35-100-P-10S-PIG, HNR4.0-35-100-P-6S-VCF, HNR4.0-35-100-P-NS-0,HNR4.0-35-100-P-NS-DAV, HNR4.0-35-100-P-NS-SIM1, HNR4.0-35-100-P-NS-SIM2, HNR4.0-35-100-ST-10S-0, HNR4.0-35-100-ST-10S-PIG, HNR4.0-35-100-ST-6S-PED, HNR4.0-35-110-P-10S-PIG, HNR4.0-35-120-P-6S-PED, HNR4.0-35-125-P-10S-0, HNR4.0-35-125-P-10S-PIG, HNR4.0-35-50-P-NS-0, HNR4.0-35-65-P-8S-VCF, HNR4.0-35-70-P-10S-0, HNR4.0-35-70-P-10S-PIG, HNR4.0-35-70-P-10S-PIG, HNR4.0-35-70-P-10S-PIG, HNR4.0-35-70-P-10S-0, HNR4.0-35-70-P-10S-0, HNR4.0-35-90-P-10S-OP-10S-PIG, HNR4.0-35-90-P-10S-PIG, HNR4.0-35-90-P-10S-OP-10

Beacon' Tip Torcon NB' Advantage Catheter

Product Catalog Numbers

HNBR4.0-35-100-P-NS-0, HNBR4.0-35-100-P-NS-C1, HNBR4.0-35-100-P-NS-C2, HNBR4.0-35-100-P-NS-CANADA-041480, HNBR4.0-35-100-P-NS-DAV, HNBR4.0-35-100-P-NS-H1, HNBR4.0-35-100-P-NS-JB1, HNBR4.0-35-100-P-NS-JB2,HNBR4.0-35-100-P-NS-JB3, HNBR4.0-35-100-P-NS-JIM, HNBR4.0-35-100-P-NS-KMP, HNBR4.0-35-100-P-NS-MPA, HNBR4.0-35-100-P-NS-O1, HNBR4.0-35-100-P-NS-SIM1, HNBR4.0-35-100-P-NS-SIM2, HNBR4.0-P-NS-SIM2, HNBR NS-SIM3,HNBR4.0-35-100-P-NS-VERT, HNBR4.0-35-100-P-NS-VTK, HNBR4.0-35-100-P-NS-WNBG, HNBR4.0-35-125-P-NS-0,HNBR4.0-35-125-P-NS-DAV, HNBR4.0-35-125-P-NS-H1, HNBR4.0-35-125-P-NS-JB1, HNBR4.0-35-125-P-NS-JB2,HNBR4.0-35-125-P-NS-MPA, HNBR4.0-35-125-P-NS-SIM2, HNBR4.0-35-125-P-NS-VERT, HNBR4.0-35-125-P-NS-VTK,HNBR4.0-35-125-P-NS-WNBG, HNBR4.0-35-40-P-NS-KMP, HNBR4.0-35-65-P-NS-0, HNBR4.0-35-65-P-NS-C1,HNBR4.0-35-65-P-NS-C2, HNBR4.0-35-65-P-NS-C3, HNBR4.0-35-65-P-NS-DAV, HNBR4.0-35-65-P-NS-H1, HNBR4.0-35-65-P-NS-JB1, HNBR4.0-35-65-P-NS-KMP, HNBR4.0-35-65-P-NS-MPA, HNBR4.0-35-65-P-NS-RC1, HNBR4.0-35-65-P-NS-RC2,HNBR4.0-35-65-P-NS-RDC, HNBR4.0-35-65-P-NS-RIM, HNBR4.0-35-65-P-NS-SIM1, HNBR4.0-35-65-P-NS-SIM2,HNBR4.0-35-80-P-NS-C1, HNBR4.0-35-80-P-NS-C2, HNBR4.0-35-80-P-NS-JL2, HNBR4.0-35-80-P-NS-JL2.5,HNBR4.0-35-80-P-NS-JL3, HNBR4.0-35-80-P-NS-JR1, HNBR4.0-35-80-P-NS-JR2, HNBR4.0-35-80-P-NS-JR3.5,HNBR4.0-35-80-P-NS-RH, HNBR4.0-35-80-P-NS-RLG, HNBR4.0-35-80-P-NS-VS, HNBR4.0-35-80-P-NS-VS1,HNBR4.0-35-80-P-NS-VS2, HNBR4.0-35-80-P-NS-VS3, HNBR4.0-NT-100-P-NS-H1, HNBR4.0-NT-80-P-NS-RC1,HNBR4.0-NT-80-P-NS-RIM, HNBR4.0-NT-80-P-NS-RLG, HNBR4.1-35-100-P-NS-0, HNBR4.1-35-100-P-NS-C1, HNBR4.1-35-100-P-NS-C2, HNBR4.1-35-100-P-NS-DAV, HNBR4.1-35-100-P-NS-H1, HNBR4.1-35-100-P-NS-JB1,HNBR4.1-35-100-P-NS-JB2, HNBR4.1-35-100-P-NS-JB3, HNBR4.1-35-100-P-NS-KMP HNBR4.1-35-100-P-NS-MPA,HNBR4.1-35-100-P-NS-O1, HNBR4.1-35-100-P-NS-SIM1, HNBR4.1-35-100-P-NS-SIM2, HNBR4.1-35-100-P-NS-SIM3,HNBR4.1-35-100-P-NS-VERT, HNBR4.1-35-100-P-NS-WNBG, HNBR4.1-35-110-P-NS-JB1, HNBR4.1-35-110-P-NS-JB2,HNBR4.1-35-110-P-NS-WNBG, HNBR4.1-35-120-P-NS-JB2, HNBR4.1-35-130-P-NS-DAV-T, HNBR4.1-35-40-P-NS-KMP,HNBR4.1-35-65-P-NS-C1, HNBR4.1-35-65-P-NS-C2, HNBR4.1-35-65-P-NS-DAV, HNBR4.1-35-65-P-NS-H1, HNBR4.1-35-65-P-NS-JB1,HNBR4.1-35-65-P-NS-KMP, HNBR4.1-35-65-P-NS-LEV1, HNBR4.1-35-65-P-NS-MPA, HNBR4.1-35-65-P-NS-RC1,HNBR4.1-35-65-P-NS-RC2, HNBR4.1-35-65-P-NS-RDC HNBR4.1-35-65-P-NS-RIM, HNBR4.1-35-65-P-NS-SHK1.0,HNBR4.1-35-65-P-NS-SIM1, HNBR4.1-35-75-P-NS-CHG-D, HNBR4.1-35-80-P-NS-C1, HNBR4.1-35-80-P-NS-C2, HNBR4.1-35-80-P-NS-JL2, HNBR4.1-35-80-P-NS-JL2.5, HNBR4.1-35-80-P-NS-JL3, HNBR4.1-35-80-P-NS-JR1, HNBR4.1-35-80-P-NS-JR2, HNBR4.1-35-80-P-NS-JR3.5, HNBR4.1-35-80-P-NS-RC1, HNBR4.1-35-80-P-NS-RH, HNBR4.1-35-80-P-NS-RLG, HNBR4.1-35-80-P-NS-VS, HNBR4.1-35-80-P-NS-VS2, HNBR4.1-NT-100-P-NS-H1,HNBR4.1-NT-80-P-NS-C1, HNBR4.1-NT-80-P-NS-RC1 HNBR4.1-NT-80-P-NS-RH, HNBR4.1-NT-80-P-NS-RIM, HNBR4.1-NT-80-P-NS-RLG, HNBR5.0-35-65-P-NS-RUC, HNBR5.0-35-90-P-NS-RUC

ΑII

Lots

Shuttle Select Slip-Cath Catheter

Product Catalog Numbers

SCBR4.5-35-135-P-NS-ANG-SHTL, SCBR4.5-35-135-P-NS-ANG-SHTL-JP, SCBR4.5-35-150-P-NS-0-SHTL, SCBR4.5- All 35-150-P-NS-ANG-SHTL, SCBR4.5-35-75-P-NS-ANG-SHTL, SCBR5.0-35-90-P-NS-RUC Lots

Slip-Cath Beacon Tip Catheter

Product Catalog Numbers

SCBR4.0-35-150-P-NS-0, SCBR4.0-35-65-P-NS-RC2, SCBR4.0-38-100-P-NS-0, SCBR4.0-38-100-P-NS-C2, SCBR4.0-38-100-P-NS-AV,SCBR4.0-38-100-P-NS-H1, SCBR4.0-38-100-P-NS-HN4, SCBR4.0-38-100-P-NS-JB1, SCBR4.0-38-100-P-NS-JB2,SCBR4.0-38-100-P-NS-KMP, SCBR4.0-38-100-P-NS-MNA, SCBR4.0-38-100-P-NS-MPA, SCBR4.0-38-100-P-NS-SIM3, SCBR4.0-38-100-P-NS-SIM3, SCBR4.0-38-100-P-NS-VERT, SCBR4.0-38-125-P-NS-DAV, SCBR4.0-38-125-P-NS-JB1, SCBR4.0-38-All 125-P-NS-SIM1, SCBR4.0-38-125-P-NS-SIM2, SCBR4.0-38-125-P-NS-VERT, SCBR4.0-38-125-P-NS-VERT, SCBR4.0-38-125-P-NS-VERT, SCBR4.0-38-65-P-NS-VERT, SCBR4.0-38-65-P-NS-VERT, SCBR4.0-38-65-P-NS-C2, SCBR4.0-38-65-P-NS-C2, SCBR4.0-38-65-P-NS-C2, SCBR4.0-38-65-P-NS-C2, SCBR4.0-38-65-P-NS-C2, SCBR4.0-38-65-P-NS-C2, SCBR4.0-38-80-P-NS-VS1, SCBR4.0-38-80-P-NS-VS2, SCBR4.0-38-80-P-NS-VS1, SCBR4.0-38-80-P-NS-VS2, SCBR4.0-38-80-P-NS-VS3, SCBR4.1-35-65-P-NS-C2, SCBR4.1-35-75-P-NS-CHG2.5