Company			
Alliance Coal	Gibson County Coal South		
nspection Date:	Wednesday, July 3, 2024		
Areas Inspected:	2NW-2 Submain XC-53 to XC-55, Z Seals, CR 8650,		
Findings / Law(s) Violated:	None		
Corrective Actions Taken:	XC-53 to XC-55 was cleaned and dusted,		
Recommendation(s):	XC-7-10 walkway was cleared.1A6 transfer point needs shoveled and rock dusted.		
Inspection Date:	Tuesday, July 9, 2024		
Areas Inspected:	Production Unti #2, CR8207, MCI8891		
Findings / Law(s) Violated:	The Unit looked good!		
Corrective Actions Taken:	None		
Recommendation(s):	Train miners to properly perform gas checks. Hand rock dusting the newly cut places could be better. Keep an eye on ribs and corners.		
Inspection Date:	Wednesday, July 31, 2024		
Areas Inspected:	4A5 Panel Belt and intaker, 4B14 Panel Belt and Intake, MCI8433,CR8658		
Findings / Law(s) Violated:	75.400		
Corrective Actions Taken:	Tha accumulations were cleaned		
Recommendation(s):	: 4A5 panel belt needs cleaned under bottom rollers.		
Inspection Date:	Wednesday, August 7, 2024		
Areas Inspected:	2 Northwest SubMain belt and intake, 2 Northwest 2 Belt and Intake, 1A Belt and Intake		
Findings / Law(s) Violated:	75.403, 75.1403-5(g)		
Corrective Actions Taken:	The mine operator is addressing the issues.		
Recommendation(s):	the 2 NW submain and intake, and the 2 NW 2nd submain belts need rock dusted		
Inspection Date:	Tuesday, August 20, 2024		
Areas Inspected:	Production Unit #3		
Findings / Law(s) Violated:	75.402		
Corrective Actions Taken:	The entry was hand dusted		
Recommendation(s):	Watch for gas bleeders and bad top near injection wells.		
Inspection Date:	Wednesday, August 28, 2024		
Areas Inspected:	3A, 3B, 3C Belts and primaries		
Findings / Law(s) Violated:	None		
Corrective Actions	None		
Taken:			

Alliance Coal		Gibson County Coal South	
Inspection Date: Wednesday, September 4, 2024		•	
Areas Inspected:			
Findings / Law(s)		· ,	
Violated:	None		
Corrective Actions	Nana		
Taken:	None		
Recommendation(s):	Belt transfer points need rock dusted. Airlock all doors between aricourses that are large enough for rubber-tired vehicles to pass.		
Inspection Date:	Tuesday, September 10, 2024		
Areas Inspected:	Unit #4, CR8228, MCI 8850		
Findings / Law(s)	OTHE #4, CR0228, WICH 8830		
Violated:	None		
Corrective Actions Taken:	None		
Recommendation(s):	Cleaning along belt line just outby the feeder could be better.		
Inspection Date:	Tuesday, September 17, 2024		
Areas Inspected:		orthwest Main 2 belt and primary and XC-80 Self-rescuer cache	
Findings / Law(s)	75.202(a)	, , , , , , , , , , , , , , , , , , ,	
Violated: Corrective Actions			
Taken:	The loose coal rib was dangered off to prevent access and management is addressing the issue.		
Recommendation(s):	1 NW Main belt and 1 NW 2 Main belt need rock dusted.		
Inspection Date:	Monday, September 30, 2024		
Areas Inspected:	Z seals, 3A8 XC-11		
Findings / Law(s) Violated:	75.220(a)(1)		
Corrective Actions Taken:	Management is addressing the issue		
Recommendation(s):	(s): Z Seals could be resealed or coated.		
Inspection Date:	Friday, September 27, 2024		
Areas Inspected:	3AB Belt and primary, 3B26 Belt and primary	mary	
Findings / Law(s) Violated:	None	•	
Corrective Actions Taken:	AMS sensor was placed at a scoop charger in the 3A intake.		
Recommendation(s):	None		
Inspection Date:			
Areas Inspected:			
Findings / Law(s)			
Violated:			
Corrective Actions			
Taken:			

Company	Mine
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Recommendation(s).	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions Taken:	
Taken.	
Recommendation(s):	
Inspection Date: Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
<u> </u>	
Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
(5)	

Insp	ection Date:	
	as Inspected:	
	Findings / Law(s)	
	Violated:	
	Corrective Actions	
	Taken:	
	Recommendation(s):	
la a a	ection Date:	
	as Inspected:	
	Findings / Law(s)	
	Violated:	
	Corrective Actions	
	Taken:	
	Recommendation(s):	
	ection Date:	
	as Inspected:	
	Findings / Law(s)	
	Violated: Corrective Actions	
	Taken:	
	Tukeni	
	Recommendation(s):	
	ection Date:	
Area	as Inspected:	
	Findings / Law(s)	
	Violated:	
	Corrective Actions	
	Taken:	
	Docommondation(s)	
	Recommendation(s):	
Inch	ection Date:	
	as Inspected:	
/ 11 C	Findings / Law(s)	
	Violated:	
	Corrective Actions	
	Taken:	
	Recommendation(s):	
	1	
	ection Date:	
Area	as Inspected:	
	Findings / Law(s)	
	Violated:	
	Corrective Actions	
	Taken:	
	Recommendation(s):	

Company	Mine
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Recommendation(s).	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions Taken:	
Taken.	
Recommendation(s):	
Inspection Date: Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
<u> </u>	
Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
(5)	

Inspection Date:			
Areas Inspected:			
Findings / Law(s)			
Violated:			
Corrective Actions			
Taken:			
Tuken.			
Recommendation(s):			
` ,			
Inspection Date:			
Areas Inspected:			
Findings / Law(s)			
Violated:			
Corrective Actions			
Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s)			
Violated:			
Corrective Actions			
Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s)			
Violated: Corrective Actions			
Taken:			
Taken:			
Recommendation(s):			
necommendation(s).			
	1		
Inspection Date:			
Areas Inspected:			
Findings / Law(s)			
Violated:			
Corrective Actions			
Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s)			
Violated:			
Corrective Actions	<u> </u>		
Taken:			
Recommendation(s):			

Company		Mine
Peabody Midw	est Mining	Francisco Mine
Inspection Date:	Tuesday, July 2, 2024	
Areas Inspected:	1st East Seals	
Findings / Law(s) Violated:	MSHA ordered K-Order, NO violations from the state	
Corrective Actions Taken:	Roof fall at the seals is dangered off, and a rehabilitation plan is being implemented.	
Recommendation(s):	None	
Inspection Date:	Thursday, July 11, 2024	
Areas Inspected:	1 Northwest Main, BT5034, BT5017, DVE	35103
Findings / Law(s) Violated:	75.403, 75.400	
Corrective Actions Taken:	These areas are being addressed by the	mine operator.
Recommendation(s):	Replace intake mandoor at XC-7. Keep a alignment.	n eye on fire extinguisher inspection tags. Keep belts in proper
Inspection Date:	Thursday, August 1, 2024	
Areas Inspected:	Production Unit #3, 3L Belt and travelwa	y, UT5003
Findings / Law(s) Violated:	75.370(a)(1)	
Corrective Actions Taken:	Adjustments were made in the ventilation controls.	
Recommendation(s):	Keep ventillation controls intact.	
Inspection Date:	Thursday, August 8, 2024	
Areas Inspected:	9 Main West Belt and Intake, 4 West Travelway	
Findings / Law(s)	75.202	
Violated: Corrective Actions Taken:	The unsafe rib was pulled down.	
Recommendation(s):	the 9 West belt drive to XC-15 needs cleaned and rock dusted.	
Inspection Date:	Wednesday, August 14, 2024	
Areas Inspected:	8 West Belt and Travelway, BT5037, 504	2. 5021. 5026. dvb5011
Findings / Law(s)	i i	
Violated: Corrective Actions	None	
Taken:	None	
Recommendation(s):	Belt line needs cleaned beneath the bottom roolers.	
Inspection Date:	Thursday, August 22, 2024	
Areas Inspected:	7 West Belt and travelway, DVB5110, BT	5036, BT5019
Findings / Law(s) Violated:	75.400, 75.1403-5(g), 75.202(a)	
Corrective Actions Taken:	The B.O. bolts were dangered off, and the	e operator is addressing the issues.
Recommendation(s):	7 West belt needs cleaned, & West transfer point needs rock dusted, 7 West belt XC-37 to XC-38 could use additional roof support.	
<u> </u>		

Peabody Midw	est Mining	Francisco Mine	
nspection Date: Tuesday, August 27, 2024		•	
Areas Inspected:	Unit #1, UT5004, UT5001, 2nd NE Submain belt and primary		
Findings / Law(s) Violated:	75.204(C)(1), 75.211(d)		
Corrective Actions Taken:	The prybar was provided for the roof bolting machine, the bad roof bolt was replaced.		
Recommendation(s):	Make sure that all working faces are rock dusted within 40 feet fof the face. The unit needs cleaned and maintained.		
nspection Date: Friday, September 6, 2024			
Areas Inspected:	6 West Belt and Secondary escapeway		
Findings / Law(s) Violated:	75.1731(a)		
Corrective Actions Taken:	The roller was replaced.		
Recommendation(s):	XC-36 to the tail need claened and dusted.		
Inspection Date:	Wednesday, September 11, 2024		
Areas Inspected:	Unit #3, UT5003, UT5002		
Findings / Law(s) Violated:	75.202(a)		
Corrective Actions Taken:	The area was dangered out from access and was being roof bolted.		
Recommendation(s):	Entries 1-5 various slips are only partially roof bolted with extra slip control. Needs additional work. Unit #5 haul roads need maintenance.		
nspection Date:	Wednesday, September 18, 2024		
Areas Inspected:	5 West Main Belt and secondary escape	way, BT 5007, BT 5057, BT 5018	
Findings / Law(s) Violated:	75.400, 75.1731(a)		
Corrective Actions Taken:	The B.O. rollers were replaced, and other	er issues being addressed.	
Recommendation(s):	the 5 West Main belt needs cleaned and	d dusted from head to XC-45.	
Inspection Date:	Tuesday, September 24, 2024		
Areas Inspected:	• • • • • • • • • • • • • • • • • • • •	main belt and secondary, 4 west main belt and secondary	
Findings / Law(s) Violated:	75.1731(a), 75.1405-5(g),n75.202(a),		
Corrective Actions Taken:	B.O. rollers were flagged, B.O. roof bolts were dangered out. Management is addressing the issues.		
Recommendation(s):	1 West belt tail and 2 XC outby need cleaned and dusted. Belts need properly trained. 4W travelway XC21 22 needs more floor to roof support.		
Inspection Date:			
Areas Inspected:			
Areas Inspected: Findings / Law(s) Violated:			
Areas Inspected: Findings / Law(s)			

Company Mine		
Peabody Midwe	est Mining	Francisco Mine
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated:		
Corrective Actions		
Taken:		
Recommendation(s):		
Increation Date:		
Inspection Date:		
Areas Inspected: Findings / Law(s)		
Violated:		
Corrective Actions		
Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated: Corrective Actions		
Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated:		
Corrective Actions		
Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated: Corrective Actions		
Taken:		
Recommendation(s):		

Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Recommendation(s).	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
,	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
nceommendation(s).	
	·
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	

ompany	Mine		
Sunrise Coal	Oaktown Fuels #1 Mine		
nspection Date:	Wednesday, July 10, 2024		
reas Inspected:	Production Unit #3, KUT-07		
Findings / Law(s) Violated:	75.204(c)(1)		
Corrective Actions Taken:	The bad roof bolt was dangered out and is being addressed by the mine operator.		
Recommendation(s):	Make sure that entries are cleaner prior to machine rock dusting them.		
nspection Date:	Friday, July 26, 2024		
reas Inspected:	Wash Plant, Overlands belt, Bruceville Portal		
Findings / Law(s) Violated:	None None		
Corrective Actions Taken:	None		
Recommendation(s):	: None		
nspection Date:	Monday, July 29, 2024		
reas Inspected:	SC4 and SD4 Belt, travelway and belt drives, T8, T18, KUT11, DVB2		
Findings / Law(s) Violated:	75.1722(a)		
Corrective Actions Taken:	The guarding was repaired and management is addressing the issue.		
Recommendation(s):	SC4 belt dirveneeds cleaned and rock dusted to XC-21.		
nspection Date:	Monday, August 5, 2024		
reas Inspected:	SD4 Intake, SC4 Intake, SB4 Intake and belt		
Findings / Law(s) Violated:	75.1100-3, 75.202(a)		
Corrective Actions Taken:	The area was dangered off and mangement is addressing the issue.		
Recommendation(s):	SC4 escapeway could use some road work.		
nspection Date:	Monday, August 12, 2024		
reas Inspected:	I North 1 Belt and Intake, SA- 4 Belt and Intake		
Findings / Law(s) Violated:	None		
Corrective Actions Taken:	None		
Recommendation(s):	Recommendation(s): 1N1 Belt needs sholeved from XC-36 - XC-44. Cribs need completed at XC-69 and XC-70. 1N1 intake XC-XC-80 needs rock dusted. XC-40 rails need floor to roof support.		
nspection Date:	Monday, August 19, 2024		
reas Inspected:	Production Unit #1, UT3		
Findings / Law(s) Violated:	75.370(a)(1)		
	Stopped production and adjusted the ventilation controls.		
Corrective Actions Taken:	Stopped production and adjusted the ventilation controls.		

Sunrise Coal		Oaktown Fuels #1 Mine	
Inspection Date: Monday, August 26, 2024			
Areas Inspected:	1 North Belt and primary, ! North 1st right belt and primary, 2A & 2B & 2C belt and primary		
Findings / Law(s) Violated:	75.1731(a), 75.403, 75.403		
Corrective Actions Taken:	The ine operator is addressing the issues.		
Recommendation(s):	2B and 2C belts need rock dusted from the heads to XC-8. 1 North needs a walkway from the belt to the primary escapeway mandoor.		
Inspection Date:	Monday, September 9, 2024		
Areas Inspected:	Unit #4, LUT-04		
Findings / Law(s) Violated:	None		
Corrective Actions Taken:	None		
Recommendation(s):	Keep probes for gas spotters better promaintenance.	tected on roof bolting macines. S4-D 1st Right road needs	
Increation Date:	Monday Sontomber 16, 2024		
Inspection Date:	Monday, September 16, 2024 2D Belt, 2E Belt to XC-45, 2E Secondary		
Areas Inspected: Findings / Law(s)	2D Beit, 2E Beit to AC-45, 2E Secondary		
Violated: Corrective Actions	75.202(a)		
Taken:	The coal ribs were dangered off to prevent access and management is addressing the issue.		
Recommendation(s):	2D belt needs cleaned and dusted from the head to XC-2. 2E Belt needs spot cleaned and walkways cleared. A two foot walkway is required on both sides of the belt.		
Inspection Date: Wednesday, September 25, 2024			
Areas Inspected:	M1 Belt and Primary, M2 Belt and Primary, 1st North 1st Right Primary		
Findings / Law(s) Violated:	75.202(a), 75.402		
Corrective Actions Taken:	The affected belt line area has been dar	gered off. The ribs on 2D and 2E belt line have been taken care of.	
Recommendation(s):	M1 belt needs cleaned and rock dusted. M2 tail area needs cleaned and dusted, M1 XC-16 needs a clear walkway to access the mandoor. 1 N 1 Right belt needs dusted. M2 Primary XC-12 Ziggy bars need new cable supports.		
Inspection Date:			
Areas Inspected:			
Findings / Law(s)			
Violated:			
Corrective Actions			
Taken:			
Recommendation(s):			
Inconcetion Data			
Inspection Date:			
Areas Inspected: Findings / Law(s)			
Violated:			
Corrective Actions			
Taken:			
Recommendation(s):			

	Mi			
Sunrise Coal Oaktown Fuels #2 M				
nspection Date:	Monday, July 8, 2024			
Areas Inspected:	Old Production Unit #1 Area			
Findings / Law(s)	None			
Violated: Corrective Actions	None			
Taken:	None			
Recommendation(s):	None			
nspection Date:	Friday, August 2, 2024			
Areas Inspected:	M8 Intake and Travelway, LBT21, TD7			
Findings / Law(s) Violated:	None			
Corrective Actions	None			
Taken:				
Recommendation(s):	None			
nspection Date:	Friday, August 16, 2024			
Areas Inspected:	M7 Primary and secondary escapeways, LBT6, LUT3,T49			
Findings / Law(s) Violated:	None			
Corrective Actions	None			
Taken:				
Recommendation(s):	None			
nspection Date:	Wednesday, August 21, 2024			
Areas Inspected:	M9, M10, M11,M6 Travelways and M6 Primary, DVB13, LBT15, T35			
Findings / Law(s) Violated:	None			
Corrective Actions	None			
	None			
Taken:	M6 Primary needs rock dusted.			
Taken: Recommendation(s):	M6 Primary needs rock dusted.			
Taken: Recommendation(s): nspection Date:	M6 Primary needs rock dusted. Thursday, August 29, 2024			
Taken: Recommendation(s): Inspection Date: Areas Inspected:	M6 Primary needs rock dusted.			
Taken: Recommendation(s): nspection Date: Areas Inspected: Findings / Law(s) Violated:	M6 Primary needs rock dusted. Thursday, August 29, 2024			
Taken: Recommendation(s): Inspection Date: Areas Inspected: Findings / Law(s)	M6 Primary needs rock dusted. Thursday, August 29, 2024 M4 Promary and Secondary, LBT10, M4A Seals			
Taken: Recommendation(s): Inspection Date: Areas Inspected: Findings / Law(s) Violated: Corrective Actions	M6 Primary needs rock dusted. Thursday, August 29, 2024 M4 Promary and Secondary, LBT10, M4A Seals None None			
Taken: Recommendation(s): Inspection Date: Areas Inspected: Findings / Law(s) Violated: Corrective Actions Taken: Recommendation(s):	M6 Primary needs rock dusted. Thursday, August 29, 2024 M4 Promary and Secondary, LBT10, M4A Seals None None None			
Taken: Recommendation(s): Inspection Date: Areas Inspected: Findings / Law(s) Violated: Corrective Actions Taken: Recommendation(s):	M6 Primary needs rock dusted. Thursday, August 29, 2024 M4 Promary and Secondary, LBT10, M4A Seals None None Sunday, September 15, 2024			
Taken: Recommendation(s): nspection Date: Areas Inspected: Findings / Law(s) Violated: Corrective Actions Taken: Recommendation(s): nspection Date: Areas Inspected: Findings / Law(s)	M6 Primary needs rock dusted. Thursday, August 29, 2024 M4 Promary and Secondary, LBT10, M4A Seals None None Sunday, September 15, 2024			
Taken: Recommendation(s): Inspection Date: Areas Inspected: Findings / Law(s) Violated: Corrective Actions Taken: Recommendation(s): Inspection Date: Areas Inspected:	M6 Primary needs rock dusted. Thursday, August 29, 2024 M4 Promary and Secondary, LBT10, M4A Seals None None None Sunday, September 15, 2024 M1 primary and secondary, M2 primary and econdary, M3 Primary and secondary, MC8, BT3, BT17, LBT8			

Sunrise Coal		Oaktown Fuels #2 Mine	
Inspection Date:	Thursday, September 19, 2024		
Areas Inspected:	M10 1st Right Seals, M9 Seals, M8A Sea	ls, M7A seals	
Findings / Law(s)	None		
Violated: Corrective Actions			
Taken:	None		
Taken.			
Recommendation(s):	: Haul roads need watered		
Inspection Date:	Monday, September 23, 2024		
Areas Inspected:	S1A Seals, 2nd South submain seals, 3rd	Main South Seals	
Findings / Law(s)		Wall South Scals	
Violated:	None		
Corrective Actions	None		
Taken:	Hone		
Recommendation(s):	M7 XC-19 needs floor to roof support in	side of airlocks	
necommendation(s).	The 15 fields field to real support in	Side of difficulty	
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions			
Taken:			
Recommendation(s):			
	<u> </u>		
Inspection Date:			
Areas Inspected:			
Findings / Law(s)			
Violated:			
Corrective Actions			
Taken:			
Recommendation(s):			
_			
Inspection Date:			
Areas Inspected: Findings / Law(s)			
Violated:			
Corrective Actions			
Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s)			
Violated:			
Corrective Actions			
Taken:	 		
Recommendation(s):			

Company	Mine
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected: Findings / Law(s)	
_	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inconcetion Date:	
Inspection Date: Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	

_		cont
Insusation Dete		
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated:		
Corrective Actions		
Taken:		
Recommendation(s):		
	1	
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated:		
Corrective Actions		
Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated:		
Corrective Actions		
Taken:		
- uncon		
Recommendation(s):		
	<u> </u>	
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated:		
Corrective Actions		
Taken:		
raken:		
Pacammandation(s):		
Recommendation(s):		
	<u> </u>	
In an anti-se Date.		
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated:		
Corrective Actions		
Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated:		
Corrective Actions		
Taken:		
Recommendation(s):		

Company	Mine
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected: Findings / Law(s)	
_	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inconcetion Date:	
Inspection Date: Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	

_		cont
Insusation Dete		
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated:		
Corrective Actions		
Taken:		
Recommendation(s):		
	1	
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated:		
Corrective Actions		
Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated:		
Corrective Actions		
Taken:		
- uncon		
Recommendation(s):		
	<u> </u>	
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated:		
Corrective Actions		
Taken:		
raken:		
Pacammandation(s):		
Recommendation(s):		
	<u> </u>	
In an anti-se Date.		
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated:		
Corrective Actions		
Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s)		
Violated:		
Corrective Actions		
Taken:		
Recommendation(s):		