



Pipeline Safety Division Investigation Report

Investigation regarding: **Corbitt And Sons Construction Co**

UPPAC Database Record ID: 3053

Investigator: Mike Enlow

Report Date: 10/23/2012

Damage Date: 5/14/2012

Damage Address: 2813 W 62nd St

City: Indianapolis

County: Marion

The Parties

Excavator: **Corbitt And Sons Construction Co**

Contact:

Address: 8728 Robbins Rd, Indianapolis, In 46268

Telephone:

Facility Owner: Citizens Gas

Contact: Tony Chan

Address: 2150 Dr. Martin Luther King Jr. Street, Indianapolis, IN 46202

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Investigation regarding: Corbitt And Sons Construction Co

UPPAC Database Record ID: 3053

Damage Impact

Product release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$0

Excavator Activities/Cause of damage information:

Excavator request locates: Yes Indiana 811 ticket Number: 1205071633

Type of Equipment: Backhoe/Trackhoe

Type of work performed: Curb / Sidewalk

Synopsis: Excavator cut gas service drop during excavation for sewer line installation.

Findings: Reported by Citizens Gas; excavator did not respond nor did the gas operator after an initial notice was mailed to each. Excavator had a valid locate; however, the gas operator failed to locate or provided incorrect locate markings.

Conclusion: After having a second notice mailed to the gas operator requesting a response with over thirty (30) days extension, a finding of an operator violation has been determined for failing to locate or providing incorrect locate markings.

Violation: IC 8-1-26-18(f): Operator failed to locate or provided incorrect locate markings.



DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)

INDIANA UTILITY REGULATORY COMMISSION

Submitted to IURC-Pipeline Safety on: May 19, 2012

Who is submitting this information?

Name of person providing this information: Tony Chan (Citizens Gas)

Business address (*number and street*): 2150 Dr. M.L. King Jr. St.

City, State, and ZIP code: Indianapolis, IN 46202

Telephone number (*area code*): (317) 927-4619

Fax number (*area code*): (317) 927-4619

E-mail address: AChan@CitizensEnergyGroup.com

Excavator Information, if known

Full name: CORBITT AND SONS

Business address (*number and street*): 8728 ROBBINS RD

City, State, and ZIP code: Indianapolis, IN 46268

Telephone number (*area code*): _____

Fax number (*area code*): _____

E-mail address: _____

Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Backhoe/Trackhoe

Type of work performed: Sewer (Sanitary/Storm)

Date and Location of Damage

Date of damage (*month, day, year*): May 14, 2012

County: Marion

City: Indianapolis

Street address (*number and street, city, state, and ZIP code*):
2813 W 62ND ST

Nearest intersection: W 62ND ST & HAZELHATEN

Right of way where damage occurred: Public - City Street

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? Yes

If yes, how many affected? 1

Time to restore service (*in hours*): 0.5

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 0

Affected Facility Information

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? 24

Notification, Locating, Marking

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1205071633

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contractor

If a contractor locator, enter the company name, if known: USIC

Were facility marks visible in the area of excavation? Yes

Were facilities marked correctly? No

Type of markings used: Paint and Flags

If other, please specify: _____

Was site marked by "White Lining"? No

Were special instructions part of the locate request? No

Were maps used to complete the locate request? Yes

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? No

Did the excavator notify 911 in the event of a release of product? No

Description of Cause

Select from the list the most accurate cause for the damage: --Facility marking or location not sufficient

Additional Comments

Excavator is not at fault. Operator failed to properly locate facility. MAO 5/21/2012.