



Pipeline Safety Division Investigation Report

Investigation regarding: **Dave O'mara Contractor, Inc.**

UPPAC Database Record ID: 3111

Investigator: William Boyd

Report Date: 08/13/2012

Damage Date: 05/29/2012 10:58:52 AM

Damage Address: N Chestnut St

City: Seymour

County: Jackson

The Parties

Excavator: **Dave O'mara Contractor, Inc.**

Contact: Dave O'mara, President

Address: 1100 East O And M Avenue, North Vernon, In 47265

Telephone: (812) 346-4135

Facility Owner: Vectren

Contact: Darlene Kulhanek

Address: 1 N Main Street, Evansville, IN 47702

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Investigation regarding: Dave O'mara Contractor, Inc.

UPPAC Database Record ID: 3111

Damage Impact

Product release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 2

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$599

Excavator Activities/Cause of damage information:

Excavator request locates: Yes Indiana 811 ticket Number: 1205231479

Type of Equipment: Backhoe/Trackhoe

Type of work performed: Sewer (Sanitary/Storm)

Synopsis: A two inch plastic gas main was damaged during excavation for a sewer line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 08/10/2012. Excavator failed to maintain required clearance from the gas main with an excavator.

Conclusion: Excavator failed to maintain the required clearance with mechanized equipment.

Violation: IC 8-1-26-20(b): Failure to plan excavation to avoid damage or interference with underground facilities; Failure to maintain two (2) feet clearance with mechanized equipment.

NO

LOCATE

TICKET

PROVIDED



INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>
Office: (317) 232-2701
Facsimile: (317) 232-6758

July 13, 2012

Ms. Darlene Kulhanek
Vectren
1 N Main Street
Evansville, IN 47702

Subject: Investigation Request for Information

Date of Event: 5/29/2012

Event Location: N Chestnut St, Seymour

Facility Owner: Vectren

Excavator: Dave Omara Contractor

Other Party: N/A

Pipeline Division Case No. 3111

Dear Ms. Kulhanek:

Pursuant to Indiana Code 8-1-26, the *Indiana Damage to Underground Facilities Act*, the Pipeline Safety Division of the Indiana Utility Regulatory Commission ("Pipeline Division") is required to investigate reported incidents of alleged statutory violations involving underground pipeline safety. The purpose of this statute is to promote excavation and pipeline safety and to reduce the imminent danger to life, health, property, or loss of service associated with unsafe digging practices. Please note that the investigation does not entail determining criminal liability or a civil determination of fault or damages; however, it does determine whether any statutory violations were committed regarding public safety.

The Pipeline Division received information regarding potential statutory violations regarding the date and location referenced above. You were identified as a person or entity that might have information that would assist the Pipeline Division in its investigation. Therefore, we have contacted you in order to receive the full account of information in order to make a fair determination related to the circumstances of this incident.

We have asked all involved parties, entities and witnesses to provide *written* information within *30 days* in order to meet legal deadlines to conclude our investigation. **Please consider this letter as a formal request to receive any and all information and evidence (including a narrative, documentation, maps, photographs or any other written information) you can access regarding anything you may know about the incident referenced above.**



DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)
INDIANA UTILITY REGULATORY COMMISSION

Submitted to IURC-Pipeline Safety on: 07-19-2012

Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (*number and street*): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (*area code*): 812-491-4227

Fax number (*area code*): 812-491-4504

E-mail address: dkulhanek@vectren.com

Excavator Information, if known

Full name: Dave Omara Contractor

Business address (*number and street*): 1100 East O and M Avenue

City, State, and ZIP code: N Vernon, IN 47265

Telephone number (*area code*): 812-346-4135

Fax number (*area code*): 812-352-1235

E-mail address: Unknown

Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Backhoe/Trackhoe

Type of work performed: Drainage

Date and Location of Damage

Date of damage (month, day, year): 5-29-2012

County: Jackson

City: Seymour

Street address (number and street, city, state, and ZIP code):
Chestnut & Indianapolis (alley), Seymour, IN

Nearest intersection: same

Right of way where damage occurred: Public - Other

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? Yes

If yes, how many affected? 2

Time to restore service (in hours): 2

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 599.42

Affected Facility Information

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? _____

Notification, Locating, Marking

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1205231479

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC

Were facility marks visible in the area of excavation? Yes

Were facilities marked correctly? Yes

Type of markings used: Paint

If other, please specify: _____

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? Yes

Did the excavator notify 911 in the event of a release of product? Unknown/Other

Description of Cause

Select from the list the most accurate cause for the damage: --Failure to use hand tools where required

Additional Comments

2" plastic main severed by backhoe. Not hand exposed.



2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH


NOW DUE

\$599.42

OMARA, DAVE CONSTRUCTION
BOX 1139, 1100 E O&M AVE,
NORTH VERNON, IN 47265

Type: GAS
Invoice: FDS0016290
BillToID: 31993
Billing Date: 7/6/2012
Date of Loss: 5/29/2012
5926 103.0509

Please return this portion with your remittance.



Mail Payment To:
Vectren Utilities Holdings, Inc. VECTREN ENERGY DELIVERY OF INDIANA - NORTH
1239 Reliable Parkway
Chicago, IL 60686-0012
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5
Risk Management/Claims Department

NOW DUE
\$599.42

OMARA, DAVE CONSTRUCTION
BOX 1139, 1100 E O&M AVE,
NORTH VERNON, IN 47265

Type: GAS
Invoice: FDS0016290
BillToID: 31993
Billing Date: 7/6/2012
Date of Loss: 5/29/2012

Invoice For Costs to Repair and Reconstruct Damaged Property

Address: CHESTNUT & INDIANAPOLIS AVE, SEYMOUR

2" PLASTIC MAIN SEVERED BY BACKHOE. FAILED TO USE HAND TOOLS WHERE REQUIRED.

Material:	\$158.91
Company Labor:	\$251.84
Contract Labor:	\$0.00
Transportation/Equipment:	\$36.56
Misc:	\$0.00
Gas Loss:	\$152.11
Adjustments:	\$0.00
Payments:	\$0.00
Total:	\$599.42

5926 103.0509

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

FACILITIES DAMAGE REPORT GAS

Task No.: 103.0509

Capital Q&M (circle one)

FDS.0016290

FACILITY TYPE
 DISTRIBUTION

DATE OF DAMAGE: 5/29/12

- PROPANE
- SERVICE
- STORAGE
- TRANSMISSION (include supplemental report)

TIME OCCURRED: 11:00 AM
TIME FOUND: 11:15 AM

Cost Center No.: 5928

DAMAGE SITE ADDRESS: CHESTNUT & INDIANAPOLIS (Alley) LOT #

COUNTY Jackson CITY: Seymour STATE IN TOWNSHIP Jackson

FACILITIES DAMAGED	ORIFICE SIZE(S)	(1)	(2)	(3)
<input type="checkbox"/> FARM TAP	0.50 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> HEATER	5/8 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> MAIN	0.75 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> METER RESIDENTIAL	1.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> METER INDUSTRIAL/COMMERCIAL	1.25 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> ODORIZER	10.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> REGULATOR STATION	12.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> RELIEF VALVE	16.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> RISER	2.00 INCH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> SERVICE LINE	20.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> VALVE	3.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	4.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	5.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	6.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
IF OTHER _____	OTHER _____			

TYPE OF MATERIAL	DAMAGE TYPE	PRESSURE
<input type="checkbox"/> CAST IRON	<input checked="" type="checkbox"/> SEVERED	<input type="checkbox"/> 25 PSIG
<input type="checkbox"/> PLASTIC (HDPE)	<input type="checkbox"/> NOT CUT	<input type="checkbox"/> 40 PSIG
<input checked="" type="checkbox"/> PLASTIC (MDPE)	<input type="checkbox"/> PUNCTURE	<input type="checkbox"/> 50 PSIG
<input type="checkbox"/> STEEL	SIZE _____ X _____	<input checked="" type="checkbox"/> 65 PSIG
IF OTHER _____		<input type="checkbox"/> 60 PSIG
		<input type="checkbox"/> 6 WC (.2163)
		<input type="checkbox"/> 7 WC (.262)
		<input type="checkbox"/> OTHER _____

PROTECTION IN PLACE
 BUILDING FENCE NONE
 POST RAIL VAULT N/A
IF OTHER _____

LEAK REPORT NUMBER # 21355 EFV ACTIVATED YES NO N/S

FEED TYPE
 ONE-WAY FEED
 TWO-WAY FEED

SERVICE ORDER # 5259609

DAMAGED BY	TYPE OF CONSTRUCTION
<input type="checkbox"/> COMPANY CREW	<input type="checkbox"/> AGRICULTURE
<input checked="" type="checkbox"/> CONTRACTOR	<input type="checkbox"/> BLDG. CONSTRUCTION
<input type="checkbox"/> COUNTY	<input type="checkbox"/> BLDG. DEMOLITION
<input type="checkbox"/> DEVELOPER	<input type="checkbox"/> CABLE TV
<input type="checkbox"/> FARMER	<input type="checkbox"/> CURBS/SIDEWALKS
<input type="checkbox"/> MUNICIPALITY	<input checked="" type="checkbox"/> DRAINAGE
<input type="checkbox"/> PROPERTY OWNER/TENANT	<input type="checkbox"/> DRIVEWAY
<input type="checkbox"/> RAILROAD	<input type="checkbox"/> ELECTRIC
<input type="checkbox"/> STATE	<input type="checkbox"/> ENGINEERING/SURVEYING
<input type="checkbox"/> UNKNOWN	<input type="checkbox"/> FENCING
<input type="checkbox"/> UTILITY	<input type="checkbox"/> GRADING
<input type="checkbox"/> VEHICULAR ACCIDENT	<input type="checkbox"/> IRRIGATION
<input type="checkbox"/> IF OTHER _____	<input type="checkbox"/> LANDSCAPE
	<input type="checkbox"/> LIQUID PIPELINE
	<input type="checkbox"/> MILLING
	<input type="checkbox"/> NATURAL GAS
	<input type="checkbox"/> POLE
WORKING FOR	<input type="checkbox"/> PUBLIC TRANSIT AUTHORITY
<input checked="" type="checkbox"/> CITY <input type="checkbox"/> COUNTY <input type="checkbox"/> DEVELOPER	<input type="checkbox"/> RAILROAD MAINTENANCE
<input type="checkbox"/> PROPERTY/OWNER <input type="checkbox"/> STATE	<input type="checkbox"/> IF OTHER _____
<input type="checkbox"/> UTILITY	
<input type="checkbox"/> IF OTHER _____	

- VISUAL OBSERVATION AT DAMAGE SITE
- VISUAL OBSERVATION ABOVE GROUND BELOW GROUND
 - LOCATE APPLICABLE? YES NO N/S
 - FACILITIES PROPERLY MARKED YES NO N/S
- MARKING METHODS: CONVENTIONAL FLAGS
- NONE OFFSET PAINT STAKES WHISKERS
 - LOCATE MARKINGS FADED? YES NO N/S
 - WRONG ADDRESS REQUESTED YES NO N/S
 - FACILITIES IMPROPERLY LOCATED
 - QUALIFIED LOCATOR COULD NOT HAVE ACCURATELY LOCATED
 - INACCURATE MAPS/CARDS
 - BROKEN OR NO TRACER WIRE (PLASTIC)
 - INSULATION PREVENTING ACCURATE LOCATE
 - LOCATOR ERROR
 - FAILURE TO FOLLOW POLICY
 - INAPPROPRIATE SITE MARKING
 - INCOMPLETE LOCATES
 - MARKING OFF
 - NO LOCATES PERFORMED
 - QUALIFIED LOCATOR COULD HAVE ACCURATELY LOCATED
 - WRONG ADDRESS LOCATED
 - MARKINGS OFF BY _____ (FEET/INCHES)
 - WERE FACILITY MARKS VISIBLE YES NO
 - WAS AREA WHITE LINED? YES NO DESTROYED
 - POSITIVE RESPONSE YES NO DESTROYED
 - TOLERANCE ZONE VIOLATED YES NO
 - PART OF PROJECT YES NO

COMPANY REPRESENTATIVE ON SITE YES NO
OBSERVATION BY: Steve Gentry
NAME OF LOCATOR: _____
LOCATING ORGANIZATION _____
 CONTRACT LOCATOR
 UNKNOWN/ OTHER
 UTILITY OWNER

COPY OF MARKOUT REQUEST PROVIDED WITHIN 2 WORKING DAYS
 YES NO N/S

NOTIFICATION AND OTHER DETAILS OF LOCATE

LOCATE TICKET #: 1205231779
DATE: _____ TIME: _____ AM/PM

REGULAR REQUEST EMERGENCY REQUEST

CONTACT NAME: _____
TIME CALLED: _____ AM/PM
TIME LOCATOR ARRIVED AT SITE _____ AM/PM

LOCATE COMPANY NOTIFIED YES NO N/S

COMPANY NOTIFIED OF LOCATE NEAR CRITICAL FACILITIES
 YES NO N/S

ONE CALL CENTER
 IUPPS
 OUPS
 UNKNOWN

5/29

JUN 5 2012

45.511

DURATION OF ESCAPING GAS MINUTES 30 MIN

NUMBER OF CUSTOMERS AFFECTED: 2
TOTAL HOURS SERVICE WAS OFF 2 hr

TYPE OF EQUIPMENT

- AUGER
- BACKHOE/TRACKHOE
- BORING
- DRILLING
- EXPLOSIVES
- FARM EQUIPMENT
- GRADER/SCRAPER
- HAND TOOLS
- MILLING EQUIPMENT
- PLOW
- PROBING DEVICE
- TRENCHER
- VACUUM EQUIPMENT
- VEHICLE

DAMAGING CAUSE

- ABANDON FACILITY
- DETERIORATED FACILITY
- FACILITY COULD NOT BE FOUND/LOCATED
- FACILITY WAS NOT LOCATED/MARKED
- FAILURE TO MAINTAIN CLEARANCE
- FAILURE TO MAINTAIN MARKS
- FAILURE TO SUPPORT EXPOSED FACILITY
- FAILURE TO USE HAND TOOLS WHERE REQ
- IMPROPER BACKFILLING
- INCORRECT RECORDS/MAPS
- MARKING OR LOCATIONS NOT SUFFICIENT
- NO NOTIFICATION MADE TO ONE-CALL CENT
- ONE-CALL NOTIFICATION ERROR
- PREVIOUS DAMAGE
- WRONG INFORMATION PROVIDED

IF OTHER _____ IF OTHER _____

DID EXCAVATOR NOTIFY YOU? YES NO

EVACUATION REQUIRED? YES NO

MEDIA AT SITE? YES NO

WAS THERE IGNITION OF GAS? YES NO

INVOICE: YES NO N/S

DAMAGING PARTY

NAME: DAVE O'MARA

ADDRESS: 1100 EAST OTHM AVE

CITY/STATE/ZIP: NORTH VERBON, IN, 47265

PHONE NUMBER: 812-346-4135

PREPARED BY: Ryan Williamson DATE: _____

CONTRACTOR REPAIRS

- CONTRACTOR WORKING FOR VECTREN MADE REPAIRS AT OWNERS EXPENSE
 - YES NO N/S
- CONTRACTOR REPAIRED DAMAGE
 - YES NO N/S

NAME OF CONTRACTOR: _____

OF REGULAR HOURS _____

OF OVERTIME HOURS _____

OF REGULAR HOURS _____

CREW TYPE _____

MATERIALS OR ROAD WORK

- METER WAS REPLACED _____ (STORES CODE)
- REGULATOR WAS REPLACED _____ (STORES CODE)
- TEMPORARY ASPHALT REPAIR _____ (SQ.FT.)
- PERMANENT ASPHALT REPAIR _____ (SQ.FT.)

RIGHT OF WAY

- DEDICATED UTILITY EASEMENT
- FEDERAL UTILITY EASEMENT
- PIPELINE
- POWER/TRANSMISSION LINE
- PRIVATE - BUSINESS
- PRIVATE - EASEMENT
- PRIVATE - LAND OWNER
- PUBLIC - COUNTY ROAD
- PUBLIC - INTERSTATE HIGHWAY
- PUBLIC - OTHER
- PUBLIC - STATE HIGHWAY
- PUBLIC - CITY STREET
- UNKNOWN

PARTY TO INVOICE

NAME: DAVE O'MARA

ADDRESS: 1100 EAST OTHM AVE

CITY/STATE/ZIP: NORTH VERBON, IN, 47265

PHONE NUMBER: 812-346-4135

REVIEWED BY: [Signature] DATE: 6-1-12

NORMAL NOTICE REMARK

Ticket : 1205231479 Date: 05/23/2012 Time: 10:33 Oper: RACHEL.RICE Chan:000
 Old Tkt: 1205073459 Date: 05/07/2012 Time: 16:02 Oper: RACHEL.RICE Rev: 00A

State: IN Cnty: JACKSON Twp: JACKSON
 Cityname: SEYMOUR Inside: Y Near: N
 Subdivision:

Address :

Street : N CHESTNUT ST
 Cross 1 : 3RD ST Within 1/4 mile: Y
 Location: LOCATE THE ALLEY THAT RUNS EAST AND WEST BETWEEN CHESTNUT AND
 INDIANAPOLIS AVENUE - ALLEY RUNS PARALLEL TO 2ND AND 3RD STREETS - LOCATE FROM
 BUILDING TO BUILDING FOR THE ENTIRE ALLEY

:
 Grids : 3857B8553C

Work type : SANITARY SEWER
 Done for : CITY OF SEYMOUR
 Start date: 05/25/2012 Time: 10:45 Hours notice: 48/48 Priority: NORM
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
 Duration : UNKNOWN Depth: 8 FEET

Company : DAVE OMARA CONTRACTOR Type: CONT
 Co addr : 1100 EAST O AND M AVENUE
 City : NORTH VERNON State: IN Zip: 47265
 Caller : RACHEL RICE Phone: (812)346-4135
 Contact : CLINT BLACK Phone:
 BestTime:
 Mobile : (812)592-0523
 Fax : (812)352-1235
 Email : RACHELR@DAVEOMARA.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
 REF JOB 113157 SEYMOUR 3RD STREET - 21
 REMARK DUE TO CONSTRUCTION AND WEATHER
 Will you be white-lining the dig site area? NO
 :

Submitted date: 05/23/2012 Time: 10:33
 Members: ID0002 ID0169 ID0340 ID2981 ID4752 ID5693 ID5928 ID7053 ID8000 ID8791
 ID9596 SM

Member Name	Facility Types
AT&T - TRANSMISSION	FIBER OPTIC
COMCAST - SEYMOUR	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
IN AMERICAN WATER SEYMOUR	
INSIGHT COMMUNICATIONS - NEW ALBANY	CABLE TV
QWEST COMMUNICATIONS	FIBER OPTIC
SCHNECK MEDICAL CENTER	FIBER OPTIC
SEYMOUR WATER POLLUTION CONTROL FACILITY SEWER	

DAMAGE SEE REMARKS

Ticket : 1205291511 Date: 05/29/2012 Time: 10:53 Oper: CPARMERLEE Chan:042

State: IN Cnty: JACKSON Twp: JACKSON
 Cityname: SEYMOUR Inside: Y Near: N
 Subdivision:

Address :
 Street : N CHESTNUT ST
 Cross 1 : 3RD ST Within 1/4 mile: Y
 Location: LOCATE THE ALLEY THAT RUNS EAST AND WEST BETWEEN CHESTNUT AND INDIANAPOLIS AVENUE - ALLEY RUNS PARALLEL TO 2ND AND 3RD STREETS - LOCATE FROM BUILDING TO BUILDING FOR THE ENTIRE ALLEY
 :
 Grids : 3857B8553C 3857B8553B

Work type : SANITARY SEWER
 Done for : CITY OF SEYMOUR
 Start date: 05/29/2012 Time: 10:53 Hours notice: 0/000 Priority: EMER
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
 Duration : UNKNOWN Depth: 8 FEET

Company : DAVE OMARA CONTRACTOR Type: CONT
 Co addr : 1100 EAST O AND M AVENUE
 City : NORTH VERNON State: IN Zip: 47265
 Caller : RACHEL RICE Phone: (812)346-4135
 Contact : CLINT BLACK Phone:
 BestTime:
 Mobile : (812)592-0686
 Fax : (812)352-1235
 Email : RACHELR@DAVEOMARA.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
 PER RACHEL: A VECTREN GAS LINE HAS BEEN CUT AND IT IS BLOWING--IN THE ALLEY BETWEEN CHESTNUT AND INPLS AVE---3/4 OR 2 INCH LINE--THAT IS ALL INFO SHE HAS--NO COLOR OR MATERIAL--THE CREW HAS ALREADY CALLED 911 AND VECTREN--CREW IS ON SITE--PREVIOUS TICKET 1205231479
 Will you be white-lining the dig site area? NO
 :

Submitted date: 05/29/2012 Time: 10:53
 Members: ID0002 ID0169 ID0340 ID2981 ID4752 ID5693 ID5928 ID7053 ID8000 ID8791 ID9596 SM

Member Name	Facility Types
AT&T - TRANSMISSION	FIBER OPTIC
COMCAST - SEYMOUR	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
IN AMERICAN WATER SEYMOUR	
INSIGHT COMMUNICATIONS - NEW ALBANY	CABLE TV
QWEST COMMUNICATIONS	FIBER OPTIC
SCHNECK MEDICAL CENTER	FIBER OPTIC
SEYMOUR WATER POLLUTION CONTROL FACILITY	SEWER
VECTREN -SEYMOUR	GAS
WINDSTREAM KDL	COMMUNICATIONS

[View Map](#) | [Close Map](#)

Service Order Status

Friday, June 8, 2012

Enter Service Order Number:

5259609



Banner Instance: CS03PROD CS01PROD CS02PROD
Order Number: N5259609
Order Type: LEAK
Order Status: Completed

Customer: 008888888 - INACTIVE CUSTOMER
Prem: 5713006 - CHESTNUT & INDIANAPOLIS AVE

Technician: 5874 - Wischmeier, Ryan

Order Dates and Times

Need Date: 5/29/2012 11:14:00 AM
Time Created: 5/29/2012 11:10:47 AM
Time Dispatched: 5/29/2012 11:10:48 AM
Time In Route: 5/29/2012 11:22:36 AM
Time On-Site: 5/29/2012 11:28:11 AM
Tech Complete: 5/29/2012 12:19:22 PM
Time Closed: 5/29/2012 12:19:22 PM

Events Performed/Completion Code

LKNS - CMP

Meter Information

Current ReadStatus

Old Meter:
New Meter:

Completion Notes

FOUND CREW ALREADY ONSITE. 2" PLASTIC MAIN WAS CUT IN ALLEY BY CONTRACTOR. CREW ONSITE TO MAKE LEAK REAPIRS. LEAK REPORT #21355.. LEFT OK.


Request Notes

PER AMBER WITH 811, HIT LINE IN ALLEY AT THIS INTERSECTION...BLOWING...DAVEOMARA CONTRACTORS ONSITE.
 ..LOCATE #1205231479.... JACKSON CTY....PHONE812-592-0686....AMBERS #317-893-1416.....THANKS

MDSI Event Dates and Times

Event	Date/Time	User
AsnAssignmentManualAck_evt	5/29/2012 11:22:22 AM	Wischmeier, Ryan
AsnAssignmentEnRoute_evt	5/29/2012 11:22:36 AM	Wischmeier, Ryan
AsnAssignmentOnSite_evt	5/29/2012 11:28:11 AM	Wischmeier, Ryan
OrdOrderComplete_evt	5/29/2012 12:19:22 PM	Wischmeier, Ryan

NOTE:The Reporting database replicates in near real-time; it has been approximately 1 minute(s) since the last transaction replicated.



Dave O'Mara Contractor, Inc.
1100 East O & M Avenue, PO Box 1139
North Vernon, Indiana 47265

Phone: 812.346.4135

www.daveomara.com

Fax: 812.346.6305

VIA E-MAIL

August 10, 2012

Pipeline Safety Division – Case No. 3111
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 E
Indianapolis, Indiana 46204
PipelineDamageCase@urc.in.gov

RE: Notice of Preliminary Determination of Violation
Pipeline Safety Division Case No. 3111 – Information Request

To Whom It May Concern:

This letter and the documents submitted herewith are the response of Dave O'Mara Contractors, Inc. ("DOCI") to a letter, dated July 13, 2012, from David L. Welch, Assistant General Counsel of the Pipeline Safety Division of the Indiana Utility Regulatory Commission.

Please note that any further information or communication with respect to this matter should be directed to Jessica A. Hill, Graydon Head & Ritchey LLP, 7759 University Drive, Suite A, West Chester, Ohio 45069.

DOCI'S RESPONSES TO THE PIPELINE SAFETY DIVISION OF THE
INDIANA UTILITY REGULATORY COMMISSION'S INFORMATION REQUESTS

1. Event Location (i.e. where this occurrence took place):

Response: This occurrence took place at N Chestnut Street, Seymour, Indiana 47274. The property is located in Jackson Township within Jackson County.

2. The Parties:

▪ Person Responsible for Excavation/Demolition (i.e. Excavator/Person that

was digging):

Response: Jim Martin
Dave O'Mara Contractor, Inc.
1100 East O & M Avenue
North Vernon, Indiana 47265
812-346-4135
rachelr@daveomara.com

- Facility Information (i.e. the Owner/Operator of the utility line):

Response: Vectren Energy Delivery of Indiana North
1239 Reliable Parkway
Chicago, IL 60686-0012
877-902-2934

- Locator Service Information (i.e. company assigned to mark the utility lines, if any):

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI has discovered no information responsive to this request and believes that there no other individuals or entities involved.

- Other (Witness, Police, fire, Other) Information:

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI has discovered no information responsive to this request and believes that there no other individuals or entities involved.

3. Utility Line Impact

- Facility Type: What type of Utility facility was involved?

Response: The facility type involved was gas.

- Material Type: What type of facility material was involved?

Response: The type of facility material was plastic.

- Size (Diameter/etc.): What was the size (diameter/etc.) of the facility material involved?

Response: The diameter of the facility material was two (2) inches.

- Pressure (PSIG/Inches): What was the pressure (PSIG/Inches) in the facility?

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI believes that the pressure within the facility was low.

- Utility Line Function: What was the function of the utility line?

Response: The utility line involved was a main gas line.

- Interruption in Service: Was service interrupted?

Response: There was minimal release of product at most.

- Number of Customers Affected: How many customers were affected?

Response: There were no customers affected.

- Evacuation: Was there an evacuation?

Response: There was no need for an evacuation, and therefore, no evacuation occurred.

- Repair Cost (if known): What are the costs/damages?

Response: The cost to repair was \$599.42. The invoice from Vectren Energy Delivery of Indiana – North is enclosed.

4. Cause of Damage Information

- Type of Equipment: What type of equipment was involved?

Response: The equipment used was an excavator.

- Type of Work Performed: What was the purpose of the work involved at the time of the event?

Response: DOCI was performing sanitary sewer work.

- Release of Product: Was there a release of product? Type? How much?

Response: Because damage to the gas line was insignificant, there was a minimal release of product at most.

- Ignition and/or Fire: Was there any ignition? Fire?

Response: There was not any ignition or fire involved.

- Excavator Notify 811: Did the excavator notify 811 Office? If not, who did?

Response: Yes, 811 was notified after the incident occurred.

5. Locate Information

- Excavator Request Locate: Did excavator make a locate request? What is the Request Ticket Number from Indiana 811?

Response: Yes, the excavator did make a locate request. The Request Ticket Number from Indiana 811 is 1205231479. A copy of the Request Ticket Number 1205231479 is attached.

- Locate Marks Visible: Were locate marks visible?

Response: Yes, the locate marks were visible.

- Excavator "White Lined": Did the excavator "white line"?

Response: No, the excavator did not "white line."

- Maps Used to Mark Facilities: Were maps used to help mark facilities?

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI has discovered no information responsive to this request.

- Was Locate Provided within Two (2) Working Days?

Response: Yes, locate was provided within two working days.

- Operator Employees On-site: Were operator's employees on site at the time of the incident?

Response: Yes, the entire crew for this project was on-site at the time of the incident.

6. Incident Impact Information

- Number of Outpatient Treated: How many patients were treated through out-patient treatment?

Response: There were no injuries or fatalities related to this incident, and therefore, there were no patients treated through out-patient treatment.

- Number of Inpatient Treated: How many patients were treated through in-patient treatment?

Response: There were no injuries or fatalities related to this incident, and therefore, there were no patients treated through in-patient treatment.

- Fatalities: Were there fatalities? If so, how many?

Response: There were no fatalities as a result of this incident.

- Fire Department Response: Was local Fire Department[s] called? Which department? Describe their response.

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI believes that the local fire department was not called in regards to this incident.

- Police Department Response: Was local Police Department[s] called? Which ones? Describe their response.

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI believes that the local police department was not called in regards to this incident.

- Ambulance Response: Was local Ambulance Service[s] called? Which ones? Describe their response.

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI believes that the local

ambulance service was not called in regards to this incident.

- Other Response: Was anyone else involved? If so, please describe.

Response: There was no one else involved in this incident.

7. Narrative Statement: In your own words, please describe what happened (regarding all parties involved) and why?

Response: There is no additional information or comments that DOCI would like to make at this time.

This concludes the response of DOCI to the foregoing request regarding Pipeline Safety Division Case No. 3111.

Sincerely,

DAVE O'MARA CONTRACTORS, INC.
1100 East O & M Avenue
North Vernon, Indiana 47265
812-346-4135

By: 
Dave O'Mara
Title: President
Date: August 10, 2012

Enclosures
3301871.1

NORMAL NOTICE REMARK

Ticket : 1205231479 Date: 05/23/2012 Time: 10:33 Oper: RACHEL.RICE Chan:000
 Old Tkt: 1205073459 Date: 05/07/2012 Time: 16:02 Oper: RACHEL.RICE Rev: 00A

State: IN Cnty: JACKSON Twp: JACKSON
 Cityname: SEYMOUR Inside: Y Near: N
 Subdivision:

Address :
 Street : N CHESTNUT ST
 Cross 1 : 3RD ST Within 1/4 mile: Y
 Location: LOCATE THE ALLEY THAT RUNS EAST AND WEST BETWEEN CHESTNUT AND
 INDIANAPOLIS AVENUE - ALLEY RUNS PARALLEL TO 2ND AND 3RD STREETS - LOCATE FROM
 BUILDING TO BUILDING FOR THE ENTIRE ALLEY
 :
 Grids : 3857B8553C

Work type : SANITARY SEWER
 Done for : CITY OF SEYMOUR
 Start date: 05/25/2012 Time: 10:45 Hours notice: 48/48 Priority: NORM
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
 Duration : UNKNOWN Depth: 8 FEET

Company : DAVE OMARA CONTRACTOR Type: CONT
 Co addr : 1100 EAST O AND M AVENUE
 City : NORTH VERNON State: IN Zip: 47265
 Caller : RACHEL RICE Phone: (812)346-4135
 Contact : CLINT BLACK Phone:
 BestTime:
 Mobile : (812)592-0523
 Fax : (812)352-1235
 Email : RACHELR@DAVEOMARA.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
 REF JOB 113157 SEYMOUR 3RD STREET - 21
 REMARK DUE TO CONSTRUCTION AND WEATHER
 Will you be white-lining the dig site area? NO
 :


Submitted date: 05/23/2012 Time: 10:33
 Members: ID0002 ID0169 ID0340 ID2981 ID4752 ID5693 ID5928 ID7053 ID8000 ID8791
 ID9596 SM

Member Name	Facility Types
AT&T - TRANSMISSION	FIBER OPTIC
COMCAST - SEYMOUR	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
IN AMERICAN WATER SEYMOUR	
INSIGHT COMMUNICATIONS - NEW ALBANY	CABLE TV
QWEST COMMUNICATIONS	FIBER OPTIC
SCHNECK MEDICAL CENTER	FIBER OPTIC
SEYMOUR WATER POLLUTION CONTROL FACILITY SEWER	

VECTREN -SEYMOUR
WINDSTREAM KDL

GAS
COMMUNICATIONS

[[View Map](#)] [[Close Map](#)]



JUL 1 12 12

NOW DUE

2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH

\$599.42

OMARA, DAVE CONSTRUCTION
BOX 1139, 1100 E O&M AVE,
NORTH VERNON, IN 47265

Type: GAS
Invoice: FDS0016290
BillToID: 31993
Billing Date: 7/6/2012
Date of Loss: 5/29/2012
5926 103.0509

Please return this portion with your remittance.



Mail Payment To:
Vectren Utilities Holding Group Inc
1239 Reliable Parkway
Chicago, IL 60686-0012
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5
Risk Management/Claims Department

NOW DUE

\$599.42

OMARA, DAVE CONSTRUCTION
BOX 1139, 1100 E O&M AVE,
NORTH VERNON, IN 47265

Type: GAS
Invoice: FDS0016290
BillToID: 31993
Billing Date: 7/6/2012
Date of Loss: 5/29/2012

Invoice For Costs to Repair and Reconstruct Damaged Property

Address: CHESTNUT & INDIANAPOLIS AVE, SEYMOUR

2" PLASTIC MAIN SEVERED BY BACKHOE. FAILED TO USE HAND TOOLS
WHERE REQUIRED.

R.L.
7/26/12

Material:	\$158.91
Company Labor:	\$251.84
Contract Labor:	\$0.00
Transportation/Equipment:	\$36.56
Misc:	\$0.00
Gas Loss:	\$152.11
Adjustments:	\$0.00
Payments:	\$0.00
<hr/> Total:	<hr/> \$599.42

5926 103.0509

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.