



Pipeline Safety Division Investigation Report

Investigation regarding: Lunar Excavating

UPPAC Database Record ID: 3372

Investigator: Howard Friend

Report Date: 9/27/2012

Damage Date: 7/16/2012 10:11:49 AM

Damage Address: 15752 Hawks Way

City: Carmel

County: Hamilton

The Parties

Excavator: **Lunar Excavating**

Contact: Dan Bedwell

Address: 8121 East 274th Street, Arcadia, In 46030

Telephone:

Facility Owner: Vectren

Contact: Darlene Kulhanek

Address: 1 N Main Street, Evansville, IN 47702

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Investigation regarding: Lunar Excavating

UPPAC Database Record ID: 3372

Damage Impact

Product release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$1678

Excavator Activities/Cause of damage information:

Excavator request locates: Yes Indiana 811 ticket Number: 1206051455

Type of Equipment: Backhoe/Trackhoe

Type of work performed: Water

Synopsis: A natural gas main was damaged during excavation for a water line.

Findings: Reported by Indiana 811; excavator did not respond to initial notice mailed 8/16/2012. The excavator provided notice of excavation on 6/5/12 and damaged the natural gas main 41 days later.

Conclusion: There was a failure to provide notice of excavation.

Violation: IC 8-1-26-16(g): Failure to provide notice of excavation.




Date: 08/23/2012

MAIL MAIL:

The following is in response to your 08/23/2012 request for delivery information on your Certified Mail(TM)/RRE item number 9214 8901 0661 5400 0002 6828 66. The delivery record shows that this item was delivered on 08/23/2012 at 12:23 PM in ARCADIA, IN 46030. The scanned image of the recipient information is provided below.

Signature of Recipient:

Delivery Section	
Signature	
Printed name	Brad Mann

Address of Recipient:

Address	ARCADIA IN 46030
Delivery address	

Thank you for selecting the Postal Service for your mailing needs. If you require additional assistance, please contact your local Post Office or postal representative.

Sincerely,

United States Postal Service

The customer reference info shown below is not validated or endorsed by the United States Postal Service. It is solely for customer use.

3372
DAN BEDWELL
LUNAR CONSTRUCTION
8121 E 274TH ST
ARCADIA IN 46030-9516



INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>
Office: (317) 232-2701
Facsimile: (317) 232-6758

August 16, 2012

Ms. Darlene Kulhanek
Vectren
1 N Main Street
Evansville, IN 47702

Subject: Investigation Request for Information

Date of Event: 7/16/2012

Event Location: 15752 Hawks Way, Carmel

Facility Owner: Vectren

Excavator: Lunar Excavating

Other Party: N/A

Pipeline Division Case No. 3372

Dear Ms. Kulhanek:

Pursuant to Indiana Code 8-1-26, the *Indiana Damage to Underground Facilities Act*, the Pipeline Safety Division of the Indiana Utility Regulatory Commission ("Pipeline Division") is required to investigate reported incidents of alleged statutory violations involving underground pipeline safety. The purpose of this statute is to promote excavation and pipeline safety and to reduce the imminent danger to life, health, property, or loss of service associated with unsafe digging practices. Please note that the investigation does not entail determining criminal liability or a civil determination of fault or damages; however, it does determine whether any statutory violations were committed regarding public safety.

The Pipeline Division received information regarding potential statutory violations regarding the date and location referenced above. You were identified as a person or entity that might have information that would assist the Pipeline Division in its investigation. Therefore, we have contacted you in order to receive the full account of information in order to make a fair determination related to the circumstances of this incident.

We have asked all involved parties, entities and witnesses to provide *written* information within *30 days* in order to meet legal deadlines to conclude our investigation. **Please consider this letter as a formal request to receive any and all information and evidence (including a narrative, documentation, maps, photographs or any other written information) you can access regarding anything you may know about the incident referenced above.**



DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)
INDIANA UTILITY REGULATORY COMMISSION

Submitted to IURC-Pipeline Safety on: 08-22-2012

Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (*number and street*): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (*area code*): 812-491-4227

Fax number (*area code*): 812-491-4504

E-mail address: dkulhanek@vectren.com

Excavator Information, if known

Full name: Lunar Construction

Business address (*number and street*): 8121 E 274th Street

City, State, and ZIP code: Arcadia, IN 46030

Telephone number (*area code*): 317-984-3782

Fax number (*area code*): Unknown

E-mail address: Unknown

Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Backhoe/Trackhoe

Type of work performed: Water

Date and Location of Damage

Date of damage (month, day, year): 7-16-2012

County: Hamilton

City: Carmel

Street address (number and street, city, state, and ZIP code):
15752 hawks Way, Carmel, IN

Nearest intersection: Unknown

Right of way where damage occurred: Dedicated Public Utility Easement

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? No

If yes, how many affected? 0

Time to restore service (in hours): 0

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 1,678.65

Affected Facility Information

What type of pipeline was damaged? Natural Gas

What was the affected facility? Distribution

What was the depth of the facility, in inches? _____

Notification, Locating, Marking

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1206051455

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC _____

Were facility marks visible in the area of excavation? Yes

Were facilities marked correctly? Yes

Type of markings used: Paint

If other, please specify: _____

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? No

Did the excavator notify Indiana 811 in the event of this damage? Yes


Did the excavator notify 911 in the event of a release of product? Unknown/Other

Description of Cause

Select from the list the most accurate cause for the damage: --Failure to use hand tools where required

Additional Comments

2" plastic main damaged by hoe. no valid locates and not hand exposed. Contractor claims had main exposed.



2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH


NOW DUE

\$1,678.65

LUNAR CONSTRUCTION
319 G GREAT LAKES DRIVE,
NOBLESVILLE, IN 46060

Type: GAS
Invoice: FDS0016560
BillToID: 32355
Billing Date: 8/15/2012
Date of Loss: 7/16/2012
5830 103.0509

Please return this portion with your remittance.



Mail Payment To:
Vectren Utilities Holding Company
1239 Reliable Parkway
Chicago, IL 60686-0012
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5
Risk Management/Claims Department

LUNAR CONSTRUCTION
319 G GREAT LAKES DRIVE,
NOBLESVILLE, IN 46060

Type: GAS
Invoice: FDS0016560
BillToID: 32355
Billing Date: 8/15/2012
Date of Loss: 7/16/2012

NOW DUE
\$1,678.65

Invoice For Costs to Repair and Reconstruct Damaged Property

Address: 15752 HAWKS WAY, CARMEL

2" PLASTIC MAIN DAMAGED BY HOE. NO VALID LOCATES AND FAILURE TO MAINTAIN CLEARANCE.

Material:	\$26.45
Company Labor:	\$111.65
Contract Labor:	\$1,045.50
Transportation/Equipment:	\$21.25
Misc:	\$0.00
Gas Loss:	\$473.80
Adjustments:	\$0.00
Payments:	\$0.00
<hr/> Total:	\$1,678.65

5830 103.0509

Remember, call two (2) working days before digging. Contact I.U.P.S. at 1-800-382-5544.

FACILITIES DAMAGE REPORT GAS

Task No.: _____ Capital / O&M (circle one)

FDS 0016560

FACILITY TYPE

TIME OCCURRED: 10:25 AM/PM
TIME FOUND: 10:36 AM/PM

DATE OF DAMAGE: 7/16/12

- DISTRIBUTION
- PROPANE
- SERVICE
- STORAGE
- TRANSMISSION (include supplemental report)

LATITUDE _____
LONGITUDE _____

Cost Center No.: 5830

DAMAGE SITE ADDRESS: 15752 HAWKS WAY LOT # _____

COUNTY HAMILTON CITY: CARMEL STATE: IN TOWNSHIP _____

FACILITIES DAMAGED	ORIFICE SIZE(S)	(1)	(2)	(3)
<input type="checkbox"/> FARM TAP	0.50 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> HEATER	5/8 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> MAIN	0.75 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> METER RESIDENTIAL	1.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> METER INDUSTRIAL/COMMERCIAL	1.25 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> ODORIZER	10.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> REGULATOR STATION	12.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> RELIEF VALVE	16.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> RISER	2.00 INCH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> SERVICE LINE	20.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> VALVE	3.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	4.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	5.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	6.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
IF OTHER _____	OTHER _____			

- VISUAL OBSERVATION AT DAMAGE SITE 7/16
- VISUAL OBSERVATION ABOVE GROUND BELOW GROUND
 - LOCATE APPLICABLE? YES NO N/S
 - FACILITIES PROPERLY MARKED YES NO N/S
 - MARKING METHODS: CONVENTIONAL FLAGS NONE OFFSET PAINT STAKES WHISKERS
 - LOCATE MARKINGS FADED: YES NO N/S
 - WRONG ADDRESS REQUESTED YES NO N/S
 - FACILITIES IMPROPERLY LOCATED
 - QUALIFIED LOCATOR COULD NOT HAVE ACCURATELY LOCATED
 - INACCURATE MAPS/CARDS
 - BROKEN OR NO TRACER WIRE (PLASTIC)
 - INSULATION PREVENTING ACCURATE LOCATE
 - LOCATOR ERROR
 - FAILURE TO FOLLOW POLICY
 - INAPPROPRIATE SITE MARKING
 - INCOMPLETE LOCATES
 - NO LOCATES PERFORMED
 - QUALIFIED LOCATOR COULD HAVE ACCURATELY LOCATED
 - WRONG ADDRESS LOCATED
 - MARKINGS OFF BY _____ (FEET/INCHES)

1.382

Made SAFE 12:12 pm

TYPE OF MATERIAL	DAMAGE TYPE	PRESSURE
<input type="checkbox"/> CAST IRON	<input type="checkbox"/> SEVERED	<input type="checkbox"/> 25 PSIG
<input type="checkbox"/> PLASTIC (HDPE)	<input type="checkbox"/> NOT CUT	<input type="checkbox"/> 40 PSIG
<input checked="" type="checkbox"/> PLASTIC (MDPE)	<input type="checkbox"/> PUNCTURE	<input type="checkbox"/> 50 PSIG
<input type="checkbox"/> STEEL	SIZE 1 X 1.5	<input type="checkbox"/> 55 PSIG
		<input checked="" type="checkbox"/> 60 PSIG
		<input type="checkbox"/> 6 WC (.2163)
		<input type="checkbox"/> 7 WC (.252)
		<input type="checkbox"/> OTHER _____

46.989

- WERE FACILITY MARKS VISIBLE YES NO
- WAS AREA WHITE LINED? YES NO DESTROYED
- POSITIVE RESPONSE YES NO DESTROYED
- TOLERANCE ZONE VIOLATED YES NO
- PART OF PROJECT YES NO

- PROTECTION IN PLACE
- BUILDING FENCE NONE
 - POST RAIL VAULT N/A

DURATION OF ESCAPING GAS
MINUTES 1 HOUR 42 MIN

LEAK REPORT NUMBER # _____ EFV ACTIVATED YES NO
 N/S

NUMBER OF CUSTOMERS AFFECTED: 0
TOTAL HOURS SERVICE WAS OFF 0

COMPANY REPRESENTATIVE ON SITE YES NO
OBSERVATION BY: DAVID ENDICOTT
NAME OF LOCATOR: _____
LOCATING ORGANIZATION _____
 CONTRACT LOCATOR
 UNKNOWN/ OTHER
 UTILITY OWNER

- FEED TYPE
- ONE-WAY FEED
 - TWO-WAY FEED

SERVICE ORDER # N5308568

- COPY OF MARKOUT REQUEST PROVIDED WITHIN 2 WORKING DAYS
- YES NO N/S

DAMAGED BY TYPE OF CONSTRUCTION

- COMPANY CREW
- CONTRACTOR
- COUNTY
- DEVELOPER
- FARMER
- MUNICIPALITY
- PROPERTY OWNER/TENANT
- RAILROAD
- STATE
- UNKNOWN
- UTILITY
- VEHICULAR ACCIDENT
- IF OTHER _____
- AGRICULTURE
- BLDG. CONSTRUCTION
- BLDG. DEMOLITION
- CABLE TV
- CURBS/SIDEWALKS
- DRAINAGE
- DRIVEWAY
- ELECTRIC
- ENGINEERING/SURVEYING
- FENCING
- GRADING
- IRRIGATION
- LANDSCAPE
- LIQUID PIPELINE
- MILLING
- NATURAL GAS
- POLE
- PUBLIC TRANSIT AUTHORITY
- RAILROAD MAINTENANCE

NOTIFICATION AND OTHER DETAILS OF LOCATE

- LOCATE TICKET #: _____
- DATE: _____ TIME: _____ AM/PM
- REGULAR REQUEST EMERGENCY REQUEST
- CONTACT NAME: _____
- TIME CALLED: _____ AM/PM
- TIME LOCATOR ARRIVED AT SITE _____ AM/PM
- LOCATE COMPANY NOTIFIED YES NO N/S
- COMPANY NOTIFIED OF LOCATE NEAR CRITICAL FACILITIES YES NO N/S

- WORKING FOR
- CITY COUNTY DEVELOPER
 - PROPERTY/OWNER STATE
 - UTILITY

- ONE CALL CENTER
- IUPPS
 - OUPS
 - UNKNOWN

IF OTHER WATER SERVICE

Coronado Homes

TYPE OF EQUIPMENT	DAMAGING CAUSE
<input type="checkbox"/> AUGER	<input type="checkbox"/> ABANDON FACILITY
<input checked="" type="checkbox"/> BACKHOE/TRACKHOE	<input type="checkbox"/> DETERIORATED FACILITY
<input type="checkbox"/> BORING	<input type="checkbox"/> FACILITY COULD NOT BE FOUND/LOCATED
<input type="checkbox"/> DRILLING	<input type="checkbox"/> FACILITY WAS NOT LOCATED/MARKED
<input type="checkbox"/> EXPLOSIVES	<input type="checkbox"/> FAILURE TO MAINTAIN CLEARANCE
<input type="checkbox"/> FARM EQUIPMENT	<input type="checkbox"/> FAILURE TO MAINTAIN MARKS
<input type="checkbox"/> GRADER/SCRAPER	<input type="checkbox"/> FAILURE TO SUPPORT EXPOSED FACILITY
<input type="checkbox"/> HAND TOOLS	<input checked="" type="checkbox"/> FAILURE TO USE HAND TOOLS WHERE REQ
<input type="checkbox"/> MILLING EQUIPMENT	<input type="checkbox"/> IMPROPER BACKFILLING
<input type="checkbox"/> PLOW	<input type="checkbox"/> INCORRECT RECORDS/MAPS
<input type="checkbox"/> PROBING DEVICE	<input type="checkbox"/> MARKING OR LOCATIONS NOT SUFFICIENT
<input type="checkbox"/> TRENCHER	<input type="checkbox"/> NO NOTIFICATION MADE TO ONE-CALL CENT
<input type="checkbox"/> VACUUM EQUIPMENT	<input type="checkbox"/> ONE-CALL NOTIFICATION ERROR
<input type="checkbox"/> VEHICLE	<input type="checkbox"/> PREVIOUS DAMAGE
	<input type="checkbox"/> WRONG INFORMATION PROVIDED
<input type="checkbox"/> IF OTHER _____	<input type="checkbox"/> IF OTHER _____

DID EXCAVATOR NOTIFY YOU? YES NO

EVACUATION REQUIRED? YES NO

MEDIA AT SITE? YES NO

WAS THERE IGNITION OF GAS? YES NO

INVOICE: YES NO N/S

CONTRACTOR REPAIRS

CONTRACTOR WORKING FOR VECTREN MADE REPAIRS AT OWN EXPENSE
 YES NO N/S

CONTRACTOR REPAIRED DAMAGE
 YES NO N/S

NAME OF CONTRACTOR: _____

OF REGULAR HOURS _____

OF OVERTIME HOURS _____

OF REGULAR HOURS _____

CREW TYPE _____

MATERIALS OR ROAD WORK

METER WAS REPLACED _____ (STORES CODE)

REGULATOR WAS REPLACED _____ (STORES CODE)

TEMPORARY ASPHALT REPAIR _____ (SQ.FT.)

PERMANENT ASPHALT REPAIR _____ (SQ.FT.)

RIGHT OF WAY

DEDICATED UTILITY EASEMENT

FEDERAL UTILITY EASEMENT

PIPELINE

POWER/TRANSMISSION LINE

PRIVATE - BUSINESS

PRIVATE - EASEMENT

PRIVATE - LAND OWNER

PUBLIC - COUNTY ROAD

PUBLIC - INTERSTATE HIGHWAY

PUBLIC - OTHER

PUBLIC - STATE HIGHWAY

PUBLIC - CITY STREET

UNKNOWN

DAMAGING PARTY

NAME: LUNAR CONST.

ADDRESS: 8121 E. 274

CITY/STATE/ZIP: ARCADIA, IN.

PHONE NUMBER: 317-984-3782

DAVID ENDICOTT 7-16-12

PREPARED BY DATE

PARTY TO INVOICE

NAME: _____

ADDRESS: _____

CITY/STATE/ZIP: _____

PHONE NUMBER: _____

[Signature] 7-31-12

REVIEWED BY FIELD SUPERVISOR DATE

* Old ticket expired

* refresh #
 (CALLED TODAY) (7/16/12)
 (NOT good until the 18th)

Contractor stated "Had gas line Exposed"

Kulhanek, Darlene T.

From: Rooker, Gary E.
Sent: Tuesday, August 14, 2012 7:44 AM
To: Kulhanek, Darlene T.
Subject: RE: FDS0016560 7-16-12 15752 Hawks Way, Carmel

1" x 1.5" hole

*Gary Rooker
Vectren Energy Delivery
Operations Supervisor
317-776-5544
765-716-1649*

From: Kulhanek, Darlene T.
Sent: Tuesday, August 14, 2012 7:21 AM
To: Rooker, Gary E.
Subject: FDS0016560 7-16-12 15752 Hawks Way, Carmel

2" main, need damage type (severed, punctured size). Thanks!

Ticket Portal Production

Ticket Text Photos

Ticket Text

ATTIN Seq: 402 Transmitted: Tue Jun 19 08:11:45 CDT 2012
 SBCIN 00393 IUPPSa 06/19/2012 09:03:33 1206051455-01A NORM 2NDR STRT
 SECOND NOTICE SECOND NOTICE
 Ticket : 1206051455 Date: 06/19/2012 Time: 09:01 Oper: TFRICKE Chan:028
 Old Tkt: 1206051455 Date: 06/05/2012 Time: 10:33 Oper: SPEOPLES Rev: 00A
 State: IN Cnty: HAMILTON Twp: WASHINGTON
 Cityname: CARMEL Inside: Y Near: N
 Subdivision: BRIDGEWATER CLUB ACRES Lot: G86
 Address : 15752
 Street : HAWKS WAY
 Cross 1 : GOLF CLUB BLVD Within 1/4 mile: Y
 Location: LOCATE THE ENTIRE PROPERTY - PLEASE PAINT AND FLAG
 :
 Grids : 4001D8605B 4001D8605A
 Boundary: n 40.018230 s 40.016830 w -86.095871 e -86.094124
 Work type : WATER AND SEWER LINE INSTALLATION
 Done for : CORONADO HOME CORPORATIONS
 Start date: 06/07/2012 Time: 10:45 Hours notice: 0/0 Priority: NORM
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
 Duration : 2 DAYS Depth: 3 FEET
 Company : LUNAR CONSTRUCTION Type: CONT
 Co addr : 8121 EAST 274TH STREET
 City : ARCADIA State: IN Zip: 46030
 Caller : AMANDA OYLER Phone: (317)984-3782
 Contact : NO Phone:
 BestTime:
 Fax : (317)984-2689
 Email : AMANDA@LUNARINDY.COM
 Remarks : All tickets are taken and processed on Eastern Daylight Time
 PER AMANDA - STILL NEED VECTREN - ONLY - TO RESPOND - CREW IS ON SITE
 Will you be white-lining the dig site area? NO
 :
 Submitted date: 06/19/2012 Time: 09:01
 Members: BE ID0002 ID0103 ID0202 ID0660 ID8000 SBCIN SM

 Email_From: att-tickets@tickets.translore.com
 Email_Subject: ATT Translore - 1206051455
 Email_Sent_Date: 2012-06-19 08:11:45 CDT
 Email_MessageID: <1340111505705.2127797603.TransLore.att-tickets@tickets.translore.com>
 Email_host: tickets3.811tickets.com
 Email_user: 811.in.att
 Email_To: 811.in.att@tickets.811tickets.com
 Email_ContentType: text/plain; charset=ISO-8859-1

NORMAL NOTICE

Ticket : 1207160817 Date: 07/16/2012 Time: 09:35 Oper: CJODOM Chan:056

State: IN Cnty: HAMILTON Twp: WASHINGTON
 Cityname: CARMEL Inside: Y Near: N
 Subdivision: BRIDGEWATER CLUB ACRES Lot: G86

Address : 15752
 Street : HAWKS WAY
 Cross 1 : GOLF CLUB BLVD Within 1/4 mile: Y
 Location: LOCATE THE ENTIRE PROPERTY - PLEASE PAINT AND FLAG
 :
 Grids : 4000A8605B 4001D8605B 4000A8605A 4001D8605A

Work type : INSTALL WATER
 Done for : CORONADO HOME CORPORATIONS
 Start date: 07/18/2012 Time: 09:45 Hours notice: 48/048 Priority: NORM
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
 Duration : 2 DAYS Depth: 3 FEET

Company : LUNAR CONSTRUCTION Type: CONT
 Co addr : 8121 EAST 274TH STREET
 City : ARCADIA State: IN Zip: 46030
 Caller : AMANDA OYLER Phone: (317)984-3782
 Contact : DAN BEDWELL - CELL Phone:
 BestTime:
 Mobile : (317)443-0331
 Email : AMANDA@LUNARINDY.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
 Will you be white-lining the dig site area? NO
 :

Submitted date: 07/16/2012 Time: 09:35
 Members: BE ID0002 ID0103 ID0202 ID0660 ID8000 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BUCKEYE	PIPELINE
COMCAST NORTHEAST (NOBLESVILLE)	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
VECTREN - NOBLESVILLE #1	GAS
WESTFIELD UTILITIES	SEWER & WATER

[View Map](#)

[Close Map](#)

DAMAGE SEE REMARKS

Ticket : 1207161069 Date: 07/16/2012 Time: 10:06 Oper: DSEGO Chan:087

State: IN Cnty: HAMILTON Twp: WASHINGTON
 Cityname: CARMEL Inside: Y Near: N
 Subdivision: BRIDGEWATER CLUB ACRES Lot: G86

Address : 15752
 Street : HAWKS WAY
 Cross 1 : GOLF CLUB BLVD Within 1/4 mile: Y
 Location: LOCATE THE ENTIRE PROPERTY - PLEASE PAINT AND FLAG

Grids : 4000A8605B 4001D8605B 4000A8605A 4001D8605A

Work type : INSTALL WATER
 Done for : CORONADO HOME CORPORATIONS
 Start date: 07/16/2012 Time: 10:07 Hours notice: 0/000 Priority: EMER
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
 Duration : 2 DAYS Depth: 3 FEET

Company : LUNAR CONSTRUCTION Type: CONT
 Co addr : 8121 EAST 274TH STREET
 City : ARCADIA State: IN Zip: 46030
 Caller : DAN BEDWELL Phone: (317)984-3782
 Contact : DAN BEDWELL---CELL Phone:
 BestTime:
 Mobile : (317)443-0331
 Email : AMANDA@LUNARINDY.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
 A VECTREN GAS LINE HAS BEEN DAMAGED ON THE NORTH SIDE OF THE PROPERTY---GAS LINE
 IS LEAKING AND CAN BE HEARD BUT IS NOT SMELLED---DAMAGED LINE IS A APPROX 2 INCH
 POLLY YELLOW LINE---DAN BEDWELL WILL CALL 911 AND HAS ALREADY NOTIFIED VECTREN
 OF THE DAMAGE---CREW IS ON SITE---PREVIOUS TICKET NUMBER 1207160817
 Will you be white-lining the dig site area? NO

Submitted date: 07/16/2012 Time: 10:06
 Members: BE ID0002 ID0103 ID0202 ID0660 ID8000 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BUCKEYE	PIPELINE
COMCAST NORTHEAST (NOBLESVILLE)	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
VECTREN - NOBLESVILLE #1	GAS
WESTFIELD UTILITIES	SEWER & WATER

[View Map](#)

[Close Map](#)

Service Order Status

Tuesday, August 14, 2012

Enter Service Order Number:

5308568



Clear Form

Refresh Data

Banner Instance: CS03PROD CS01PROD CS02PROD

Order Number: N5308568

Order Type: LEAK

Order Status: Completed

Customer: 600559021 - CORONADO CUSTOM HOMES

Prem: 5706177 - 15752 HAWKS WAY

Technician: 2245 - Endicott, David

Order Dates and Times

Need Date: 7/16/2012 10:30:00 AM
Time Created: 7/16/2012 10:22:34 AM
Time Dispatched: 7/16/2012 10:22:34 AM
Time In Route: 7/16/2012 10:23:59 AM
Time On-Site: 7/16/2012 10:36:05 AM
Tech Complete: 7/16/2012 12:27:58 PM
Time Closed: 7/16/2012 12:27:58 PM

Events Performed/Completion Code

LKNS - CMP

Meter Information

Current ReadStatus

Old Meter:

New Meter:

Completion Notes

MAIN MADE SAFE---MILLER CREW ON SITE

Request Notes

PER DELISE WITH 811/HIT 2 INCH POLY YELLOW LINE/LEAKING/HIT BY LUNAR CONSTRUCT DON BEDWELL 317 443 0 331/XST: GOLFCLUB BLVD/LOCATE 1207160817/DAM TICKET1207161069....

MDSI Event Dates and Times

Event	Date/Time	User
AsnAssignmentManualAck_evt	7/16/2012 10:23:56 AM	Endicott, David
AsnAssignmentEnRoute_evt	7/16/2012 10:23:59 AM	Endicott, David
AsnAssignmentOnSite_evt	7/16/2012 10:36:05 AM	Endicott, David
OrdOrderComplete_evt	7/16/2012 12:27:58 PM	Endicott, David

NOTE:The Reporting database replicates in near real-time; it has been approximately 1 minute(s) since the last transaction replicated.

Ticket Detail: 1206051455



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206051455	20120619154212_10 08995.jpg	Jun 19, 2012 2:48 PM CDT	Pratt, Kurt	6/19/12 3:42 PM	



Property of United States Infrastructure Corporation
Photo taken on 6/19/2012 3:42:12 PM

Ticket Detail: 1206051455



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206051455	20120619154214_10 08996.jpg	Jun 19, 2012 2:47 PM CDT	Pratt, Kurt	6/19/12 3:42 PM	



Property of United States Infrastructure Corporation
Photo taken on 6/19/2012 3:42:14 PM

Ticket Detail: 1206051455



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206051455	20120619154218_10 08997.jpg	Jun 19, 2012 2:47 PM CDT	Pratt, Kurt	6/19/12 3:42 PM	



Property of United States Infrastructure Corporation
Photo taken on 6/19/2012 3:42:18 PM



Attachments

Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206051455	20120619154200_10_08990.jpg	Jun 19, 2012 2:48 PM CDT	Pratt, Kurt	6/19/12 3:41 PM	



Property of United States Infrastructure Corporation
Photo taken on 6/19/2012 3:42:00 PM

Ticket Detail: 1206051455



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206051455	20120619154202_10 08991.jpg	Jun 19, 2012 2:48 PM CDT	Pratt, Kurt	6/19/12 3:42 PM	



Property of United States Infrastructure Corporation
Photo taken on 6/19/2012 3:42:02 PM

Ticket Detail: 1206051455



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206051455	20120619154204_10 08992.jpg	Jun 19, 2012 2:48 PM CDT	Pratt, Kurt	6/19/12 3:42 PM	



Property of United States Infrastructure Corporation
Photo taken on 6/19/2012 3:42:04 PM

Ticket Detail: 1206051455



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206051455	20120619154208_10 08993.jpg	Jun 19, 2012 2:48 PM CDT	Pratt, Kurt	6/19/12 3:42 PM	



Property of United States Infrastructure Corporation
Photo taken on 6/19/2012 3:42:08 PM

Ticket Detail: 1206051455



Attached to	Name	Upload Date	Uploaded by	Created	Position
Ticket 1206051455	20120619154210_10 08994.jpg	Jun 19, 2012 2:48 PM CDT	Pratt, Kurt	6/19/12 3:42 PM	



Property of United States Infrastructure Corporation
Photo taken on 6/19/2012 3:42:10 PM