



## Pipeline Safety Division Investigation Report

### Investigation regarding: **Dave O'mara Contractor, Inc.**

UPPAC Database Record ID: 3411

Investigator: Howard Friend

Report Date: 9/27/2012

Damage Date: 7/26/2012 8:14:36 AM

Damage Address: 1694 Bell Ford Dr S

City: Seymour

County: Jackson

### The Parties

Excavator: **Dave O'mara Contractor, Inc.**

Contact: Dave O'mara, Vice President

Address: 1100 East O And M Avenue, North Vernon, In 47265

Telephone:

Facility Owner: Vectren

Contact: Darlene Kulhanek

Address: 1 N Main Street, Evansville, IN 47702

### Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

**Investigation regarding: Dave O'mara Contractor, Inc.**

UPPAC Database Record ID: 3411

**Damage Impact**

Product release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$669

**Excavator Activities/Cause of damage information:**

Excavator request locates: Yes Indiana 811 ticket Number: 1207160079

Type of Equipment: Directional Drilling

Type of work performed: Water

**Synopsis:** A natural gas main was damaged during excavation to install a water line.

**Findings:** Reported by Indiana 811; excavator's response to initial notice was received on 9/14/2012. The excavator had a valid locate request and the operator provided accurate locate markings. The excavator failed to maintain two (2) feet of clearance with mechanized equipment

**Conclusion:** Excavator failed to maintain the required clearance with mechanized equipment.

**Violation: IC 8-1-26-20(b): Failure to plan excavation to avoid damage or interference with underground facilities; Failure to maintain two (2) feet clearance with mechanized equipment.**



Dave O'Mara Contractor, Inc.  
1100 East O & M Avenue, PO Box 1139  
North Vernon, Indiana 47265  
www.daveomara.com

Phone: 812.346.4135

Fax: 812.346.6305

---

**VIA E-MAIL**

August 21, 2012

Pipeline Safety Division – Case No. 3411  
Indiana Utility Regulatory Commission  
101 West Washington Street, Suite 1500 E  
Indianapolis, Indiana 46204  
PipelineDamageCase@urc.in.gov

RE: Notice of Preliminary Determination of Violation  
Pipeline Safety Division Case No. 2648 – Information Request

To Whom It May Concern:

This letter and the documents submitted herewith are the response of Dave O'Mara Contractors, Inc. ("DOCI") to a letter, dated February 24, 2012, from William Boyd, Director of the Pipeline Safety Division of the Indiana Utility Regulatory Commission.

Please note that any further information or communication with respect to this matter should be directed to Jessica A. Hill, Graydon Head & Ritchey LLP, 7759 University Drive, Suite A, West Chester, Ohio 45069.

**DOCI'S RESPONSES TO THE PIPELINE SAFETY DIVISION OF THE  
INDIANA UTILITY REGULATORY COMMISSION'S INFORMATION REQUESTS**

1. The Parties:

▪ Excavator Information:

Response: Dave O'Mara Contractor, Inc.  
Randy Hammons, Project Foreman  
1100 East O & M Avenue  
P.O. Box 1139  
North Vernon, Indiana 47265  
Preferred Phone: 812-346-4135

Cell Phone: 812-592-0501  
randyh@daveomara.com

- Facility Information:

Response: Vectren Utilities Holding  
Vectren Energy Delivery of Indiana - North  
1239 Reliable Parkway  
Chicago, IL 60686  
1-877-902-2934

- Locator Service Information:

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI has discovered no information responsive to this request.

- Other (Witness, Police, fire, Other) Information:

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI has discovered no information responsive to this request and believes that there no other individuals or entities involved.

## 2. Utility Line Impact:

- Location of Damage:

Response: 1694 Bell Ford Road  
Seymour, IN 47274  
The nearest intersection is State Road 11.

- Product Type:

Response: The product type involved was natural gas.

- Facility Type:

Response: Main

- Size (Diameter/etc.):

Response: The diameter of the facility material was 2 inch, the color was yellow, the material type was poly and the pressure of the line was 60 PSI.

- Pressure (PSIG/Inches):

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI does not know the pressure that was within the facility.

- Interruption in Service:

Response: There was not an interruption in service.

- Number of Customers Affected:

Response: There were no customers affected.

- Evacuation:

Response: There was no need for an evacuation, and therefore, no evacuation occurred.

- Repair Cost (if known):

Response: The cost to repair was \$668.67. The invoice from Vectren Energy Delivery of Indiana – North is enclosed.

### 3. Cause of Damage Information:

- Type of Equipment:

Response: The type of equipment used was a Direction Drilling Machine.

- Type of Work Performed:

Response: DOCI was performing directional drilling work.

- Release of Product:

Response: There was a minimal release of product at most.

- Ignition and/or Fire:

Response: There was not any ignition or fire involved.

- Excavator Notify 811:

Response: Yes, 811 was notified after the incident occurred.

#### 4. Locate Information:

- Excavator Request Locate:

Response: Yes, the excavator did make a locate request. The Request Ticket Number from Indiana 811 is 1207160079. A copy of the Request Ticket Number 1207160079 is enclosed.

- Locate Marks Visible:

Response: Yes, the locate marks were visible.

- Locate Marks Correct:

Response: Yes, the locate marks were correct.

- Excavator "White Lined":

Response: No, the excavator did not "white line."

- Maps Used to Mark Facilities:

Response: After performing a diligent search of company records and directing inquiries to company personnel most likely to have relevant information, DOCI has discovered no information responsive to this request.

- Was Locate Provided within Two (2) Working Days?

Response: Yes, locate was provided within two working days.

- Operator Employees On-site: Were operator's employees on site at the time of the incident?

Response: Yes, the entire crew for this project was on-site at the time of the incident.

#### 5. Incident Impact Information:

- Number of Outpatient Treated:

Response: There were no injuries or fatalities related to this incident, and therefore, there were no patients treated through outpatient treatment.

- Number of Inpatient Treated:

Response: There were no injuries or fatalities related to this incident, and therefore, there were no patients treated through inpatient treatment.

- Number of Fatalities:

Response: There were no fatalities as a result of this incident.

- Fire Department Response:

Response: The local fire department was not called in regards to this incident.

- Police Department Response:

Response: The local police department was not called in regards to this incident.

- Ambulance Response:

Response: The local ambulance service was not called in regards to this incident.

6. Additional Information/Comments:

Response: There is no additional information or comments that DOCI would like to make at this time.

This concludes the response of DOCI to the foregoing request regarding Pipeline Safety Division Case No. 3411.

Sincerely,

DAVE O'MARA CONTRACTORS, INC.  
1100 East O & M Avenue, P.O. Box 1139  
North Vernon, Indiana 47265  
812-346-4135

By:   
Title: Vice President  
Date: August 21, 2012

Enclosures

3565556.1




2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH

\$668.67

OMARA, DAVE CONSTRUCTION  
BOX 1139, 1100 E O&M AVE,  
NORTH VERNON, IN 47265

Type: GAS  
Invoice: FDS0016613  
BillToID: 32306  
Billing Date: 8/15/2012  
Date of Loss: 7/26/2012  
5928 103.0509

Please return this portion with your remittance.



Mail Payment To:  
Vectren Utilities Holding Company  
1239 Reliable Parkway  
Chicago, IL 60686-0012  
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5  
Risk Management/Claims Department

NOW DUE

\$668.67

OMARA, DAVE CONSTRUCTION  
BOX 1139, 1100 E O&M AVE,  
NORTH VERNON, IN 47265

Type: GAS  
Invoice: FDS0016613  
BillToID: 32306  
Billing Date: 8/15/2012  
Date of Loss: 7/26/2012

Invoice For Costs to Repair and Reconstruct Damaged Property

Address: 1694 BELL FORD DRIVE, SEYMOUR

2" PLASTIC MAIN SEVERED BY BORE. NOT HAND EXPOSED.

Material:	\$35.55
Company Labor:	\$468.05
Contract Labor:	\$0.00
Transportation/Equipment:	\$96.56
Misc:	\$0.00
Gas Loss:	\$68.51
Adjustments:	\$0.00
Payments:	\$0.00
Total:	\$668.67

RD,  
8/21/12

5928 103.0509

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

## Rachel Rice

---

**From:** Randy Hammons  
**Sent:** Tuesday, August 21, 2012 12:25 PM  
**To:** Rachel Rice  
**Subject:** Emailing: Ticket Text and Map display for Ticket # 1207160079.htm

NORMAL NOTICE

Ticket : 1207160079 Date: 07/16/2012 Time: 06:45 Oper: RANDY.HAMMONS Chan:000

State: IN Cnty: JACKSON Twp: JACKSON  
Cityname: SEYMOUR Inside: Y Near: N  
Subdivision: BELL FORD MANOR Lot: 62

Address : 1694  
Street : BELL FORD DR S  
Cross 1 : W 6TH ST Within 1/4 mile: Y  
Location: LOCATE WEST SIDE ADDRESS-AT NORTHWEST PROPERTY CORNER-BOTH SIDES OF STREET  
\*\*\*Boring Where = UNDER STREET

:  
Grids : 3857A8554A 3857A8555D

Work type : WATER SERVICE INSTALLATION  
Done for : INDIANA AMERICAN WATER  
Start date: 07/18/2012 Time: 07:00 Hours notice: 48/48 Priority: NORM  
Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N  
Duration : 1 DAY Depth: 4 FEET

Company : DAVE OMARA CONTRACTOR Type: CONT  
Co addr : 1100 EAST O AND M AVENUE  
City : NORTH VERNON State: IN Zip: 47265  
Caller : RANDY HAMMONS Phone: (812)346-4135  
Contact : RANDY HAMMONS - CELL Phone:  
BestTime:  
Mobile : (812)592-0501  
Fax : (812)524-0501  
Email : [RANDYH@DAVEOMARA.COM](mailto:RANDYH@DAVEOMARA.COM)

Remarks : All tickets are taken and processed on Eastern Daylight Time  
Will you be white-lining the dig site area? YES

:

Submitted date: 07/16/2012 Time: 06:45  
Members: ID0002 ID0340 ID2981 ID5928 ID8000 ID8791 ID9596 SM

Member Name	Facility Types
COMCAST - SEYMOUR	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
IN AMERICAN WATER SEYMOUR	
INSIGHT COMMUNICATIONS - NEW ALBANY	CABLE TV
SEYMOUR WATER POLLUTION CONTROL FACILITY	SEWER
VECTREN -SEYMOUR	GAS



INDIANA UTILITY REGULATORY COMMISSION  
101 W. WASHINGTON STREET, SUITE 1500E  
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>  
Office: (317) 232-2701  
Facsimile: (317) 232-6758

August 16, 2012

Ms. Darlene Kulhanek  
Vectren  
1 N Main Street  
Evansville, IN 47702

Subject: Investigation Request for Information

Date of Event: 7/26/2012

Event Location: 1694 / Bell Ford Dr S, Seymour

Facility Owner: Vectren

Excavator: Dave O'mara Contractor, Inc.

Other Party: N/A

Pipeline Division Case No. 3411

Dear Ms. Kulhanek:

Pursuant to Indiana Code 8-1-26, the *Indiana Damage to Underground Facilities Act*, the Pipeline Safety Division of the Indiana Utility Regulatory Commission ("Pipeline Division") is required to investigate reported incidents of alleged statutory violations involving underground pipeline safety. The purpose of this statute is to promote excavation and pipeline safety and to reduce the imminent danger to life, health, property, or loss of service associated with unsafe digging practices. Please note that the investigation does not entail determining criminal liability or a civil determination of fault or damages; however, it does determine whether any statutory violations were committed regarding public safety.

The Pipeline Division received information regarding potential statutory violations regarding the date and location referenced above. You were identified as a person or entity that might have information that would assist the Pipeline Division in its investigation. Therefore, we have contacted you in order to receive the full account of information in order to make a fair determination related to the circumstances of this incident.

We have asked all involved parties, entities and witnesses to provide *written* information within *30 days* in order to meet legal deadlines to conclude our investigation. **Please consider this letter as a formal request to receive any and all information and evidence (including a narrative, documentation, maps, photographs or any other written information) you can access regarding anything you may know about the incident referenced above.**



## DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)  
INDIANA UTILITY REGULATORY COMMISSION

Submitted to IURC-Pipeline Safety on: 08-22-2012

### Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (*number and street*): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (*area code*): 812-491-4227

Fax number (*area code*): 812-491-4504

E-mail address: dkulhanek@vectren.com

### Excavator Information, if known

Full name: Dave Omara Contractor

Business address (*number and street*): 1100 East O&M Ave, Box 1139

City, State, and ZIP code: N Vernon, IN 47265

Telephone number (*area code*): 812-346-4135

Fax number (*area code*): 812-524-0501

E-mail address: Unknown

### Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Boring

Type of work performed: Water

---

**Date and Location of Damage**Date of damage (month, day, year): 7-26-2012County: JacksonCity: SeymourStreet address (number and street, city, state, and ZIP code):  
1694 Bell Ford Drive, Seymour, INNearest intersection: UnknownRight of way where damage occurred: Dedicated Public Utility EasementWas there a release of product? YesIf yes, was there an ignition of product? NoWere evacuations necessary as a result of release? NoIf yes, how many evacuated? 0Was there a customer service interruption? NoIf yes, how many affected? 0Time to restore service (in hours): 0Enter number of injuries, if applicable and known: 0Enter number of fatalities, if applicable and known: 0Property damage, Estimate \$ 668.67

---

**Affected Facility Information**What type of pipeline was damaged? Natural GasWhat was the affected facility? Distribution

What was the depth of the facility, in inches? \_\_\_\_\_

---

**Notification, Locating, Marking**Did excavator request locates prior to commencing work? YesEnter Indiana 811 ticket number, if known: 1207160079

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC \_\_\_\_\_

Were facility marks visible in the area of excavation? Yes

Were facilities marked correctly? Yes

Type of markings used: Paint

If other, please specify: \_\_\_\_\_

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? Yes

Did the excavator notify 911 in the event of a release of product? Unknown/Other

---

### Description of Cause

Select from the list the most accurate cause for the damage: --Failure to use hand tools where required

---

### Additional Comments

2" plastic main damaged by bore. Not hand exposed.



2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH


NOW DUE

\$668.67

OMARA, DAVE CONSTRUCTION  
BOX 1139, 1100 E O&M AVE,  
NORTH VERNON, IN 47265

Type: GAS  
Invoice: FDS0016613  
BillToID: 32306  
Billing Date: 8/15/2012  
Date of Loss: 7/26/2012  
5928 103.0509

Please return this portion with your remittance.



Mail Payment To:  
Vectren Utilities Holding Company  
1239 Reliable Parkway  
Chicago, IL 60686-0012  
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5  
Risk Management/Claims Department

NOW DUE  
\$668.67

OMARA, DAVE CONSTRUCTION  
BOX 1139, 1100 E O&M AVE,  
NORTH VERNON, IN 47265

Type: GAS  
Invoice: FDS0016613  
BillToID: 32306  
Billing Date: 8/15/2012  
Date of Loss: 7/26/2012

**Invoice For Costs to Repair and Reconstruct Damaged Property**

Address: 1694 BELL FORD DRIVE, SEYMOUR  
2" PLASTIC MAIN SEVERED BY BORE. NOT HAND EXPOSED.

Material:	\$35.55
Company Labor:	\$468.05
Contract Labor:	\$0.00
Transportation/Equipment:	\$96.56
Misc:	\$0.00
Gas Loss:	\$68.51
Adjustments:	\$0.00
Payments:	\$0.00
<b>Total:</b>	<b>\$668.67</b>

5928 103.0509

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

FACILITIES DAMAGE REPORT GAS

Task No.: 103.0509

Capital / O&M (circle one)

FDS 001.0613.

FACILITY TYPE

DISTRIBUTION

PROPANE

SERVICE

STORAGE

TRANSMISSION (include supplemental report)

TIME OCCURRED: 8:30 <sup>AM/PM</sup>

TIME FOUND: 8:45 <sup>AM/PM</sup>

DATE OF DAMAGE: 7/26/12

Cost Center No.: 5928

DAMAGE SITE ADDRESS: 1694 BELL FORD Dr South LOT # \_\_\_\_\_

COUNTY JACKSON CITY: SEYMOUR STATE: IN TOWNSHIP JACKSON

FACILITIES DAMAGED	ORIFICE SIZE(S)	(1)	(2)	(3)
<input type="checkbox"/> FARM TAP	0.50 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> HEATER	5/8 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> MAIN	0.75 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> METER RESIDENTIAL	1.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> METER INDUSTRIAL/COMMERCIAL	1.25 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> ODORIZER	10.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> REGULATOR STATION	12.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> RELIEF VALVE	16.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> RISER	2.00 INCH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> SERVICE LINE	20.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> VALVE	3.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	4.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	5.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	6.00 INCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
IF OTHER _____	OTHER _____			

*1.943*

TYPE OF MATERIAL

CAST IRON

PLASTIC (HDPE)

PLASTIC (MDPE)

STEEL

DAMAGE TYPE

SEVERED

NOT CUT

PUNCTURE

SIZE 2 X 2

PRESSURE

25 PSIG

40 PSIG

50 PSIG

55 PSIG

60 PSIG

6 WC (.2163)

7 WC (.252)

OTHER \_\_\_\_\_

*46.205*

PROTECTION IN PLACE

BUILDING  FENCE  NONE

POST  RAIL  VAULT  N/A

IF OTHER \_\_\_\_\_

DURATION OF ESCAPING GAS MINUTES 15

LEAK REPORT NUMBER # 8/23/15 EFV ACTIVATED  YES  NO  N/S

FEED TYPE

ONE-WAY FEED

TWO-WAY FEED

AFFECTED: 0

TOTAL HOURS SERVICE WAS OFF 0

SERVICE ORDER # NS319089

DAMAGED BY TYPE OF CONSTRUCTION

- COMPANY CREW
- CONTRACTOR
- COUNTY
- DEVELOPER
- FARMER
- MUNICIPALITY
- PROPERTY OWNER/TENANT
- RAILROAD
- STATE
- UNKNOWN
- UTILITY
- VEHICULAR ACCIDENT
- IF OTHER \_\_\_\_\_

- AGRICULTURE
- BLDG. CONSTRUCTION
- BLDG. DEMOLITION
- CABLE TV
- CURBS/SIDEWALKS
- DRAINAGE
- DRIVEWAY
- ELECTRIC
- ENGINEERING/SURVEYING
- FENCING
- GRADING
- IRRIGATION
- LANDSCAPE
- LIQUID PIPELINE
- MILLING
- NATURAL GAS
- POLE
- PUBLIC TRANSIT AUTHORITY
- RAILROAD MAINTENANCE

IF OTHER WATER

WORKING FOR

CITY  COUNTY  DEVELOPER

PROPERTY/OWNER  STATE

UTILITY

IF OTHER \_\_\_\_\_

VISUAL OBSERVATION AT DAMAGE SITE *7/26*

VISUAL OBSERVATION  ABOVE GROUND  BELOW GROUND

LOCATE APPLICABLE?  YES  NO  N/S

FACILITIES PROPERLY MARKED  YES  NO  N/S

MARKING METHODS:  CONVENTIONAL  FLAGS

NONE  OFFSET  PAINT  STAKES  WHISKERS

LOCATE MARKINGS FADED:  YES  NO  N/S

WRONG ADDRESS REQUESTED  YES  NO  N/S

FACILITIES IMPROPERLY LOCATED

QUALIFIED LOCATOR COULD NOT HAVE ACCURATELY LOCATED

INACCURATE MAPS/CARDS

BROKEN OR NO TRACER WIRE (PLASTIC)

INSULATION PREVENTING ACCURATE LOCATE

LOCATOR ERROR

FAILURE TO FOLLOW POLICY

INAPPROPRIATE SITE MARKING

INCOMPLETE LOCATES

MARKING OFF

NO LOCATES PERFORMED

QUALIFIED LOCATOR COULD HAVE ACCURATELY LOCATED

WRONG ADDRESS LOCATED

MARKINGS OFF BY \_\_\_\_\_ (FEET/INCHES)

WERE FACILITY MARKS VISIBLE  YES  NO

WAS AREA WHITE LINED?  YES  NO  DESTROYED

POSITIVE RESPONSE  YES  NO  DESTROYED

TOLERANCE ZONE VIOLATED  YES  NO

PART OF PROJECT  YES  NO

AUG 10 2012

COMPANY REPRESENTATIVE ON SITE  YES  NO

OBSERVATION BY: \_\_\_\_\_

NAME OF LOCATOR: \_\_\_\_\_

LOCATING ORGANIZATION \_\_\_\_\_

CONTRACT LOCATOR

UNKNOWN/ OTHER

UTILITY OWNER

COPY OF MARKOUT REQUEST PROVIDED WITHIN 2 WORKING DAYS  YES  NO  N/S

NOTIFICATION AND OTHER DETAILS OF LOCATE

LOCATE TICKET #: \_\_\_\_\_ DATE: \_\_\_\_\_ TIME: \_\_\_\_\_ AM/PM

REGULAR REQUEST  EMERGENCY REQUEST

CONTACT NAME: \_\_\_\_\_ TIME CALLED: \_\_\_\_\_ AM/PM TIME LOCATOR ARRIVED AT SITE \_\_\_\_\_ AM/PM

LOCATE COMPANY NOTIFIED  YES  NO  N/S

COMPANY NOTIFIED OF LOCATE NEAR CRITICAL FACILITIES  YES  NO  N/S

ONE CALL CENTER

IUPPS

OUPS

UNKNOWN

- TYPE OF EQUIPMENT
- AUGER
  - BACKHOE/TRACKHOE
  - BORING
  - DRILLING
  - EXPLOSIVES
  - FARM EQUIPMENT
  - GRADER/SCRAPER
  - HAND TOOLS
  - MILLING EQUIPMENT
  - PLOW
  - PROBING DEVICE
  - TRENCHER
  - VACUUM EQUIPMENT
  - VEHICLE
  - IF OTHER \_\_\_\_\_

- DAMAGING CAUSE
- ABANDON FACILITY
  - DETERIORATED FACILITY
  - FACILITY COULD NOT BE FOUND/LOCATED
  - FACILITY WAS NOT LOCATED/MARKED
  - FAILURE TO MAINTAIN CLEARANCE
  - FAILURE TO MAINTAIN MARKS
  - FAILURE TO SUPPORT EXPOSED FACILITY
  - FAILURE TO USE HAND TOOLS WHERE REQ
  - IMPROPER BACKFILLING
  - INCORRECT RECORDS/MAPS
  - MARKING OR LOCATIONS NOT SUFFICIENT
  - NO NOTIFICATION MADE TO ONE-CALL CENT
  - ONE-CALL NOTIFICATION ERROR
  - PREVIOUS DAMAGE
  - WRONG INFORMATION PROVIDED
  - IF OTHER \_\_\_\_\_

- CONTRACTOR REPAIRS
- CONTRACTOR WORKING FOR VECTREN MADE REPAIRS AT OWN EXPENSE
    - YES  NO  N/S
  - CONTRACTOR REPAIRED DAMAGE
    - YES  NO  N/S

NAME OF CONTRACTOR: \_\_\_\_\_  
 # OF REGULAR HOURS \_\_\_\_\_  
 # OF OVERTIME HOURS \_\_\_\_\_  
 # OF REGULAR HOURS \_\_\_\_\_  
 CREW TYPE \_\_\_\_\_

- MATERIALS OR ROAD WORK
- METER WAS REPLACED \_\_\_\_\_ (STORES CODE)
  - REGULATOR WAS REPLACED \_\_\_\_\_ (STORES CODE)
  - TEMPORARY ASPHALT REPAIR \_\_\_\_\_ (SQ.FT.)
  - PERMANENT ASPHALT REPAIR \_\_\_\_\_ (SQ.FT.)

- RIGHT OF WAY
- DEDICATED UTILITY EASEMENT
  - FEDERAL UTILITY EASEMENT
  - PIPELINE
  - POWER/TRANSMISSION LINE
  - PRIVATE - BUSINESS
  - PRIVATE - EASEMENT
  - PRIVATE - LAND OWNER
  - PUBLIC - COUNTY ROAD
  - PUBLIC - INTERSTATE HIGHWAY
  - PUBLIC - OTHER
  - PUBLIC - STATE HIGHWAY
  - PUBLIC - CITY STREET
  - UNKNOWN

DID EXCAVATOR NOTIFY YOU?  YES  NO

EVACUATION REQUIRED?  YES  NO

MEDIA AT SITE?  YES  NO

WAS THERE IGNITION OF GAS?  YES  NO

INVOICE:  YES  NO  N/S

DAMAGING PARTY NAME: DAVE O'MARA

ADDRESS: 1100 EAST OYM AVE

CITY/STATE/ZIP: NORTH VERNON, IN 47265

PHONE NUMBER: 812-346-4135

PREPARED BY: Kym Wilschmeyer DATE \_\_\_\_\_

*SAME*  
*↑*

PARTY TO INVOICE NAME: \_\_\_\_\_

ADDRESS: \_\_\_\_\_

CITY/STATE/ZIP: \_\_\_\_\_

PHONE NUMBER: \_\_\_\_\_

REVIEWED BY FIELD SUPERVISOR: Bill Bauer 5/1/12 DATE \_\_\_\_\_

## NORMAL NOTICE

Ticket : 1207160079 Date: 07/16/2012 Time: 06:45 Oper: RANDY.HAMMONS Chan:000

State: IN Cnty: JACKSON Twp: JACKSON  
Cityname: SEYMOUR Inside: Y Near: N  
Subdivision: BELL FORD MANOR Lot: 62Address : 1694  
Street : BELL FORD DR S  
Cross 1 : W 6TH ST Within 1/4 mile: Y  
Location: LOCATE WEST SIDE ADDRESS-AT NORTHWEST PROPERTY CORNER-BOTH SIDES OF  
STREET  
\*\*\*Boring Where = UNDER STREET  
:  
Grids : 3857A8554A 3857A8555DWork type : WATER SERVICE INSTALLATION  
Done for : INDIANA AMERICAN WATER  
Start date: 07/18/2012 Time: 07:00 Hours notice: 48/48 Priority: NORM  
Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N  
Duration : 1 DAY Depth: 4 FEETCompany : DAVE OMARA CONTRACTOR Type: CONT  
Co addr : 1100 EAST O AND M AVENUE  
City : NORTH VERNON State: IN Zip: 47265  
Caller : RANDY HAMMONS Phone: (812)346-4135  
Contact : RANDY HAMMONS - CELL Phone:  
BestTime:  
Mobile : (812)592-0501  
Fax : (812)524-0501  
Email : RANDYH@DAVEOMARA.COMRemarks : All tickets are taken and processed on Eastern Daylight Time  
Will you be white-lining the dig site area? YES

:

Submitted date: 07/16/2012 Time: 06:45  
Members: ID0002 ID0340 ID2981 ID5928 ID8000 ID8791 ID9596 SM

Member Name	Facility Types
COMCAST - SEYMOUR	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
IN AMERICAN WATER SEYMOUR	
INSIGHT COMMUNICATIONS - NEW ALBANY	CABLE TV
SEYMOUR WATER POLLUTION CONTROL FACILITY	SEWER
VECTREN -SEYMOUR	GAS

[View Map](#)[Close Map](#)

DAMAGE SEE REMARKS

Ticket : 1207260344 Date: 07/26/2012 Time: 08:13 Oper: JSMITH Chan:088

State: IN Cnty: JACKSON Twp: JACKSON  
 Cityname: SEYMOUR Inside: Y Near: N  
 Subdivision: BELL FORD MANOR Lot: 62

Address : 1694  
 Street : BELL FORD DR S  
 Cross 1 : W 6TH ST Within 1/4 mile: Y  
 Location: LOCATE WEST SIDE ADDRESS-AT NORTHWEST PROPERTY CORNER-BOTH SIDES OF STREET  
 \*\*\*Boring Where = UNDER STREET  
 :  
 Grids : 3857A8554A 3857A8555D

Work type : WATER SERVICE INSTALLATION  
 Done for : INDIANA AMERICAN WATER  
 Start date: 07/26/2012 Time: 08:13 Hours notice: 0/000 Priority: EMER  
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: Y  
 Duration : 1 DAY Depth: 4 FEET

Company : DAVE OMARA CONTRACTOR Type: CONT  
 Co addr : 1100 EAST O AND M AVENUE  
 City : NORTH VERNON State: IN Zip: 47265  
 Caller : RANDY HAMMONS Phone: (812)346-4135  
 Contact : RANDY HAMMONS - CELL Phone:  
 BestTime:  
 Mobile : (812)592-0501  
 Fax : (812)524-0501  
 Email : RANDYH@DAVEOMARA.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 VECTREN GAS MAIN WAS CUT ON THE WEST SIDE OF THE PROPERTY ON THE WEST SIDE OF  
 BELL FORD DRIVE SOUTH--GAS IS BLOWING--CALLER HAS BEEN ADVISED TO CALL BOTH  
 VECTREN AND 911 TO REPORT THE DAMAGED GAS LINE--CREW IS ON SITE--CALLER  
 DESCRIBES THE LINE AS YELLOW POLY AND IS APPROX 2 INCHES IN DIAMETER--PREVIOUS  
 TICKET NUMBER IS 1207160079--THANK YOU!!  
 Will you be white-lining the dig site area? YES  
 :

Submitted date: 07/26/2012 Time: 08:13  
 Members: ID0002 ID0340 ID2981 ID5928 ID8000 ID8791 ID9596 SM

Member Name	Facility Types
COMCAST - SEYMOUR	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
IN AMERICAN WATER SEYMOUR	
INSIGHT COMMUNICATIONS - NEW ALBANY	CABLE TV
SEYMOUR WATER POLLUTION CONTROL FACILITY	SEWER
VECTREN -SEYMOUR	GAS

[View Map](#)

[Close Map](#)

# Service Order Status

Monday, August 13, 2012

**Enter Service Order Number:**

5319089



**Banner Instance:**  CS03PROD  CS01PROD  CS02PROD  
**Order Number:** N5319089  
**Order Type:** LEAK  
**Order Status:** Completed

**Customer:** 600602968 - WILLMAN RODNEY  
**Prem:** 5719123 - 1694 BELL FORD DR S

**Technician:** 5874 - Wischmeier, Ryan

**Order Dates and Times**

**Need Date:** 7/26/2012 8:29:00 AM  
**Time Created:** 7/26/2012 8:24:54 AM  
**Time Dispatched:** 7/26/2012 8:24:54 AM  
**Time In Route:** 7/26/2012 9:00:58 AM  
**Time On-Site:** 7/26/2012 9:01:00 AM  
**Tech Complete:** 7/26/2012 10:58:34 AM  
**Time Closed:** 7/26/2012 10:58:34 AM

**Events Performed/Completion Code**

LKNS - CMP

**Meter Information**

**Current ReadStatus**

**Old Meter:**  
**New Meter:**

**Completion Notes**

FOUND 2" PLASTIC MAIN WAS BORED THRU BY CONTRACTORS. HELPED CREW REPLACE DAMAGED PIPE SECTION.NO HOUSES LOST SERVICE. FDS#0016613. LEFT OK.

**Request Notes**

HIT LINE IN FIELD PER RANDY HAMMONDS WITH DAVE O'MEARA CONTRACTING. HE IS ONSITE. 812-592-0501. DID HAVE LOCATES. NO SERVICE ATTACHED AT THIS ADDRESS IS BANNER. TICKET # 1207260344 OLD TICKET # 1207160079....

**MDSI Event Dates and Times**

Event	Date/Time	User
AsnAssignmentManualAck_evt	7/26/2012 8:25:51 AM	Wischmeier, Ryan
AsnAssignmentEnRoute_evt	7/26/2012 8:31:01 AM	Wischmeier, Ryan
AsnAssignmentOnSite_evt	7/26/2012 8:40:10 AM	Wischmeier, Ryan
OrdOrderSuspend_evt	7/26/2012 8:43:13 AM	Wischmeier, Ryan
AsnAssignmentEnRoute_evt	7/26/2012 9:00:58 AM	Wischmeier, Ryan
AsnAssignmentOnSite_evt	7/26/2012 9:01:00 AM	Wischmeier, Ryan
OrdOrderComplete_evt	7/26/2012 10:58:34 AM	Wischmeier, Ryan

NOTE:The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.