



## Pipeline Safety Division Investigation Report

### Investigation regarding: **Harvey Construction**

UPPAC Database Record ID: 3698

Investigator: Howard Friend

Report Date: 10/25/2012

Damage Date: 08/31/2012 9:58:09 AM

Damage Address: Maple Run Dr

City: Sheridan

County: Hamilton

### The Parties

Excavator: **Harvey Construction**

Contact: Matt Wilson, President

Address: 9125 East 146th Street, Noblesville, In 46060

Telephone: (317) 773-7302

Facility Owner: Vectren

Contact: Darlene Kulhanek

Address: 1 N Main Street, Evansville, IN 47702

### Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

## **Investigation regarding: Harvey Construction**

UPPAC Database Record ID: 3698

### **Damage Impact**

Product release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$1200

### **Excavator Activities/Cause of damage information:**

Excavator request locates: Yes    Indiana 811 ticket Number: 1208231192

Type of Equipment: Boring

Type of work performed: Water

**Synopsis:** A natural gas main was damaged during a boring procedure to install a water line.

**Findings:** Reported by Indiana 811; excavator signed for initial notice on 09/17/2012 but has not submitted a response. Excavator failed to pothole to expose the main prior to performing a boring procedure.

**Conclusion:** Excavator failed to maintain the required clearance with mechanized equipment.

**Violation: IC 8-1-26-20(b): Failure to plan excavation to avoid damage or interference with underground facilities; Failure to maintain two (2) feet clearance with mechanized equipment.**



Date: 09/17/2012

MAIL MAIL:

The following is in response to your 09/17/2012 request for delivery information on your Certified Mail(TM)/RRE item number 9214 8901 0661 5400 0004 2855 08. The delivery record shows that this item was delivered on 09/17/2012 at 12:34 PM in NOBLESVILLE, IN 46060. The scanned image of the recipient information is provided below.

Signature of Recipient:

Delivery Section	
Signature	X <i>Matt W</i>
Printed name	<i>Matt Wilson</i>

Address of Recipient:

Address	<i>9125 E 146th St</i>
---------	------------------------

Thank you for selecting the Postal Service for your mailing needs. If you require additional assistance, please contact your local Post Office or postal representative.

Sincerely,

United States Postal Service

The customer reference info shown below is not validated or endorsed by the United States Postal Service. It is solely for customer use.

3698  
MATT WILSON  
HARVEY CONSTRUCTION  
9125 E 146TH ST  
NOBLESVILLE IN 46060-4310



INDIANA UTILITY REGULATORY COMMISSION  
101 W. WASHINGTON STREET, SUITE 1500E  
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>  
Office: (317) 232-2701  
Facsimile: (317) 232-6758

September 18, 2012

Ms. Darlene Kulhanek  
Vectren  
1 N Main Street  
Evansville, IN 47702

Subject: Investigation Request for Information

Date of Event: 8/31/2012

Event Location: Maple Run Dr, Sheridan

Facility Owner: Vectren

Excavator: Harvey Construction

Other Party: N/A

Pipeline Division Case No. 3698

Dear Ms. Kulhanek:

Pursuant to Indiana Code 8-1-26, the *Indiana Damage to Underground Facilities Act*, the Pipeline Safety Division of the Indiana Utility Regulatory Commission ("Pipeline Division") is required to investigate reported incidents of alleged statutory violations involving underground pipeline safety. The purpose of this statute is to promote excavation and pipeline safety and to reduce the imminent danger to life, health, property, or loss of service associated with unsafe digging practices. Please note that the investigation does not entail determining criminal liability or a civil determination of fault or damages; however, it does determine whether any statutory violations were committed regarding public safety.

The Pipeline Division received information regarding potential statutory violations regarding the date and location referenced above. You were identified as a person or entity that might have information that would assist the Pipeline Division in its investigation. Therefore, we have contacted you in order to receive the full account of information in order to make a fair determination related to the circumstances of this incident.

We have asked all involved parties, entities and witnesses to provide *written* information within *30 days* in order to meet legal deadlines to conclude our investigation. **Please consider this letter as a formal request to receive any and all information and evidence (including a narrative, documentation, maps, photographs or any other written information) you can access regarding anything you may know about the incident referenced above.**



# DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)  
INDIANA UTILITY REGULATORY COMMISSION

Submitted to IURC-Pipeline Safety on: 9-28-2012

## Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (*number and street*): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (*area code*): 812-491-4227

Fax number (*area code*): 812-491-4504

E-mail address: dkulhanek@vectren.com

## Excavator Information, if known

Full name: Harvey Construction

Business address (*number and street*): 9125 E 146th Street

City, State, and ZIP code: Noblesville, IN 46060

Telephone number (*area code*): 317-714-2891

Fax number (*area code*): 317-773-7565

E-mail address: Unknown

## Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Boring

Type of work performed: Water

---

**Date and Location of Damage**

Date of damage (*month, day, year*): 8-31-2012

County: Hamilton

City: Sheridan, IN

Street address (*number and street, city, state, and ZIP code*):  
Maple Run Drive 100' south of IN 47, Sheridan, IN

Nearest intersection: Unknown

Right of way where damage occurred: Dedicated Public Utility Easement

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? No

If yes, how many affected? 0

Time to restore service (*in hours*): 0

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 1,200

---

**Affected Facility Information**

What type of pipeline was damaged? Natural Gas

What was the affected facility? Distribution

What was the depth of the facility, in inches? \_\_\_\_\_

---

**Notification, Locating, Marking**

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1208231192

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC

Were facility marks visible in the area of excavation? Yes

Were facilities marked correctly? Yes

Type of markings used: Paint and Flags

If other, please specify: None

Was site marked by "White Lining"? Yes

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? Unknown/Other

Did the excavator notify 911 in the event of a release of product? Unknown/Other

---

### Description of Cause

Select from the list the most accurate cause for the damage: --Failure to use hand tools where required

---

### Additional Comments

2" plastic main damaged by bore. Not hand exposed.

FDS 016822

Task No: 103,0509 Capital (O & M) (Circle one)  
Date of Damage 8/31/12

Vectren Claim Number: \_\_\_\_\_  
Police Report / MO #: \_\_\_\_\_

Vectren Claims Camera:

VE01406  
Form 3112

Cost Center # \_\_\_\_\_  
Time Occurred 1000 am/pm  
Time Found 1032 am/pm  
Latitude 40.122078 Longitude -86.225796

# FACILITIES DAMAGE REPORT

## GAS

DAMAGE SITE:  
Address MAPLE RUN DR Lot # \_\_\_\_\_  
County WASHINGTON City SHERIDAN State IN Township ADAMS

FACILITY TYPE:  
 Distribution  Propane  
 Service  Storage  
 Transmission: (include supplemental report)

FACILITIES DAMAGED:	ORIFICE SIZE(S):	(1)	(2)	(3)
<input type="checkbox"/> Farm Tap	0.50 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Heater	5/8 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Main	0.75 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Residential)	1.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Industrial / Commercial)	1.25 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Odorizer	2.00 inch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Regulator Station	3.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Relief Valve	4.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Riser	5.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Service Line	6.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Valve	10.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	12.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	16.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Other	20.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	Other			

**VISUAL OBSERVATION AT DAMAGE SITE:**  
 Visual Observation:  Above Ground  Below Ground  
 Locate Applicable:  Yes  No  N/S  
 Facilities Properly Marked:  Yes  No  N/S  
**Marking Methods:**  Conventional  Flags  None  Whiskers  
 Offset  Paint  Stakes  
 Locate Marking Faded:  Yes  No  N/S  
 Wrong Address Requested:  Yes  No  N/S

**TYPE OF MATERIAL:**  Cast Iron  Plastic (HDPE)  Plastic (MDPE)  Steel  Other \_\_\_\_\_  
**DAMAGE TYPE:**  Severed  Not Cut  Severed  
 Size 1 x 1/4  
**PRESSURE:**  25 PSIG  40 PSIG  50 PSIG  55 PSIG  60 PSIG  6 WC (.2163)  7 WC (252)  Other \_\_\_\_\_

**Facilities Improperly Located:**  
 Qualified Locator Could Not Have Accurately Located  
 Inaccurate Maps / Cards  
 Broken or No Tracer Wire (Plastic)  
 Insulation Preventing Accurate Locate  
**Locator Error:**  
 Failure to Follow Policy  
 Inappropriate Site Markings  
 Incomplete Locate  
 No Locates Performed  
 Qualified Locator Could Have Accurately Located  
 Wrong Address Located  
 Marking Off By: \_\_\_\_\_ (Feet / Inches)

**PROTECTION IN PLACE:**  Building  Fence  None  Post  Rail  Vault  N/A  Other \_\_\_\_\_  
**DURATION OF ESCAPING GAS:**  
 Minutes: 119

Were Facility Marks Visible:  Yes  No  Destroyed  
 Was Area White Lined:  Yes  No  Destroyed  
 Positive Response:  Yes  No  Destroyed  
 Tolerance Zone Violated:  Yes  No  
 Part of Project:  Yes  No  
 Company Representative On-Site:  Yes  No

**LEAK REPORT NUMBER:** 14808  
**FEED TYPE:**  One-Way Feed  Two-Way Feed  
**SEVERITY:**  Minor  Major  Catastrophic

Observation by (ID#): 5417  
 Name of Locator: \_\_\_\_\_  
**LOCATING ORGANIZATION:**  
 Contract Locator  Unknown / Other  Utility Owner

**SERVICE ORDER NUMBER:** 5354381

**DAMAGED BY:**  Company Crew  Contractor  County  Developer  Farmer  Municipality  Property Owner/ Tenant  Railroad  State  Unknown  Utility  Vehicle Accident  Other \_\_\_\_\_  
**TYPE OF CONSTRUCTION:**  Agriculture  Building Construction  Building Demolition  Cable TV  Curbs / Sidewalk  Drainage  Driveway  Electric  Engineering / Surveying  Fencing  Grading  Irrigation  Landscaping  Liquid Pipeline  Milling  Pole  Natural Gas  Public Transit Authority  Railroad Maintenance  Other WATER LINE

**NOTIFICATIONS AND OTHER DETAILS OF LOCATE:**  
 Locate Ticket: \_\_\_\_\_  
 Date: \_\_\_\_\_ Time: \_\_\_\_\_ am / pm

**WORKING FOR:**  City  County  Developer  State  Property Owner  Utility  
 HARVEY CONSTRUCTION

**TYPE OF REQUEST:**  
 Regular Request  Emergency Request  
 Locate Company Notified  
 Contact Name: \_\_\_\_\_  
 Time Called: \_\_\_\_\_ am / pm  
 Time Locator Arrived at the Site: \_\_\_\_\_ am / pm

Company Notified of Locate Near Critical Facilities:  Yes  No  N/S  
 Copy of Mark Out Request Provided Within 2 Working Days:  Yes  No  N/S

**ONE-CALL CENTER:**  
 IUPPS  OUPS  Unknown

Vectren Claim Number: \_\_\_\_\_

**TYPE OF EQUIPMENT:**

- Auger
- Backhoe / Track hoe
- Boring
- Drilling
- Explosives
- Farm Equipment
- Grader / Scraper
- Hand Tools
- Milling Equipment
- Plow
- Probing Device
- Trencher
- Vacuum Equipment
- Vehicle
- Other \_\_\_\_\_

**ROOT DAMAGING CAUSE:**

- Abandoned Facility
- Deteriorated Facility
- Facility Could Not be Found/ Located
- Facility Was Not Located / Marked
- Failure to Maintain Clearance
- Failure to Maintain Marks
- Failure to Support Exposed Facility
- Failure to Use Hand Tools Where Required
- Improper Backfilling
- Incorrect Records / Maps
- Marking or Location Not Sufficient
- No Notification Made to One-Call
- One-Call Notification Error
- Previous Damage
- Wrong Information Provided
- Other \_\_\_\_\_

**CONTRACTOR REPAIRS:**

- Contractor Working for Vectren Made Repairs at Own Expense  
 Yes  No  N/S
- Contractor Repaired Damage  
 Yes  No  N/S

Name of Contractor: \_\_\_\_\_  
 # of Regular Hours; \_\_\_\_\_  
 # of Overtime Hours; \_\_\_\_\_  
 # of Regular Hours; \_\_\_\_\_  
 Crew Type: \_\_\_\_\_

**MATERIALS OR ROAD WORK:**

- Meter was replaced \_\_\_\_\_ (Stores Code)
- Regulator Was Replaced \_\_\_\_\_ (Stores Code)
- Temporary Asphalt Repair: \_\_\_\_\_ (sq. ft.)
- Permanent Asphalt Repair: \_\_\_\_\_ (sq. ft.)

Did Excavator Notify You

- Yes  No

Excavation Required

- Yes  No

Media at Site

- Yes  No

Was There Ignition of Gas?

- Yes  No

INVOICE:

- Yes  No  N/S

**RIGHT OF WAY:**

- Dedicated Utility Easement
- Federal Utility Easement
- Pipeline
- Power / Transmission Line
- Private - Business
- Private - Easement
- Private - Land Owner
- Public - County Road
- Public - Interstate Highway
- Public - Other
- Public - State Highway
- Public - City Street
- Unknown

**DAMAGING PARTY:**

Name: MERLIN WAGLER  
 Address: 9125 E 146<sup>TH</sup>  
 City/ State/ Zip: NOBLESVILLE IN 46060  
 Phone: (317) 773-7302  
 Prepared / Investigated By: \_\_\_\_\_ Date: \_\_\_\_\_

**PARTY TO INVOICE:**

Name: SAME  
 Address: \_\_\_\_\_  
 City/ State/ Zip: \_\_\_\_\_  
 Phone: ( ) \_\_\_\_\_  
 Reviewed by Field Supervisor: \_\_\_\_\_ Date: 9-4-12

**Kulhanek, Darlene T.**

---

**From:** Rooker, Gary E.  
**Sent:** Wednesday, September 12, 2012 2:49 PM  
**To:** Kulhanek, Darlene T.  
**Subject:** RE: FDS0016822 8-31-2012 Maple run, Sheridan

*1" x ¼ hole 119 min.*

*Gary Rooker  
Vectren Energy Delivery  
Operations Supervisor  
317-776-5544  
765-716-1649*

---

**From:** Kulhanek, Darlene T.  
**Sent:** Wednesday, September 12, 2012 8:02 AM  
**To:** Rooker, Gary E.  
**Subject:** FDS0016822 8-31-2012 Maple run, Sheridan

Gary:

I need damage size and duration gas escaped. Thanks!

NORMAL NOTICE

Ticket : 1208231192 Date: 08/23/2012 Time: 10:41 Oper: MATT.WILSON Chan:000

State: IN Cnty: HAMILTON Twp: ADAMS  
 Cityname: SHERIDAN Inside: Y Near: N  
 Subdivision: MAPLE RUN

Address :  
 Street : MAPLE RUN DR  
 Cross 1 : IN RT 47 Within 1/4 mile: Y  
 Location: FROM THE INTERSECTION PLEASE LOCATE BOTH SIDES OF MAPLE RUN DRIVE  
 HEADING SOUTH FOR 300 FEET-CONTACT JIM VERBOSKY WITH ANY QUESTIONS AT 317 714  
 2891

\*\*\*Boring Where = UNDER MAPLE RUN DRIVE 5 FEET DEEP

Grids : 4007B8613B 4007A8613B

Work type : SEWER AND WATER LINE INSTALLATION  
 Done for : WESTPORT HOMES  
 Start date: 08/27/2012 Time: 11:00 Hours notice: 96/48 Priority: NORM  
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N  
 Duration : 2 WEEKS Depth: 10 FEET

Company : HARVEY CONSTRUCTION Type: CONT  
 Co addr : 9125 EAST 146TH STREET  
 City : NOBLESVILLE State: IN Zip: 46060  
 Caller : MATT WILSON Phone: (317)773-7302  
 Contact : JIM VERBOSKY Phone:  
 BestTime:  
 Mobile : (317)714-2891  
 Fax : (317)773-7565  
 Email : MATT@HARVEYCONST.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 PLEASE PAINT AND FLAG

Will you be white-lining the dig site area? YES

Submitted date: 08/23/2012 Time: 10:41  
 Members: ID0002 ID0103 ID0660 ID1370 ID5117 ID5293 ID8000 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
CABLE DIRECT / LONGVIEW COMMUNICATIONS	CABLE TV
COMCAST NORTHEAST (NOBLESVILLE)	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FIBERTECH	FIBER OPTIC
FRONTIER	TELEPHONE
SHERIDAN WATER & SEWER UTILITIES, TOWN OF	
VECTREN - NOBLESVILLE #1	GAS

[View Map](#)

[Close Map](#)

SECOND NOTICE 2ND NOTICE

Ticket : 1208231192 Date: 08/28/2012 Time: 16:22 Oper: BBASTIN Chan:045  
 Old Tkt: 1208231192 Date: 08/23/2012 Time: 10:41 Oper: MATT.WILSON Rev: 00A

State: IN Cnty: HAMILTON Twp: ADAMS  
 Cityname: SHERIDAN Inside: Y Near: N  
 Subdivision: MAPLE RUN

Address :  
 Street : MAPLE RUN DR  
 Cross 1 : IN RT 47 Within 1/4 mile: Y  
 Location: FROM THE INTERSECTION PLEASE LOCATE BOTH SIDES OF MAPLE RUN DRIVE  
 HEADING SOUTH FOR 300 FEET-CONTACT JIM VERBOSKY WITH ANY QUESTIONS AT 317 714  
 2891

\*\*\*Boring Where = UNDER MAPLE RUN DRIVE 5 FEET DEEP

Grids : 4007B8613B 4007A8613B

Work type : SEWER AND WATER LINE INSTALLATION  
 Done for : WESTPORT HOMES  
 Start date: 08/27/2012 Time: 11:00 Hours notice: 0/000 Priority: NORM  
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N  
 Duration : 2 WEEKS Depth: 10 FEET

Company : HARVEY CONSTRUCTION Type: CONT  
 Co addr : 9125 EAST 146TH STREET  
 City : NOBLESVILLE State: IN Zip: 46060  
 Caller : MATT WILSON Phone: (317)773-7302  
 Contact : JIM VERBOSKY Phone:  
 BestTime:  
 Mobile : (317)714-2891  
 Fax : (317)773-7565  
 Email : MATT@HARVEYCONST.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 NEEDS ALL UTILITIES TO RESPOND AND FINISH MARKINGS--CALLER STATES THAT IT WAS  
 ONLY MARKED NEAR THE MANHOLE ON WEST SIDE OF ROAD BUT IT NEEDS TO BE MARKED AS  
 IT STATES IN LOCATE INSTRUCTIONS--THANK YOU  
 Will you be white-lining the dig site area? YES

Submitted date: 08/28/2012 Time: 16:22  
 Members: ID0002 ID0103 ID0660 ID1370 ID5117 ID5293 ID8000 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
CABLE DIRECT / LONGVIEW COMMUNICATIONS	CABLE TV
COMCAST NORTHEAST (NOBLESVILLE)	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FIBERTECH	FIBER OPTIC
FRONTIER	TELEPHONE
SHERIDAN WATER & SEWER UTILITIES, TOWN OF	
VECTREN - NOBLESVILLE #1	GAS

[View Map](#)

[Close Map](#)




Property of United States Infrastructure Corporation  
Photo taken on 8/30/2012 9:03:35 AM



Property of United States Infrastructure Corporation  
Photo taken on 8/30/2012 9:03:43 AM



Property of United States Infrastructure Corporation  
Photo taken on 8/31/2012 10:32:50 AM



Property of United States Infrastructure Corporation  
Photo taken on 8/31/2012 10:33:08 AM



Property of United States Infrastructure Corporation  
Photo taken on 8/31/2012 10:33:16 AM



Property of United States Infrastructure Corporation  
Photo taken on 8/31/2012 10:33:26 AM



Property of United States Infrastructure Corporation  
Photo taken on 8/31/2012 10:33:34 AM



Property of United States Infrastructure Corporation  
Photo taken on 8/31/2012 10:33:38 AM



Property of United States Infrastructure Corporation  
Photo taken on 8/31/2012 12:37:40 PM



Property of United States Infrastructure Corporation  
Photo taken on 8/31/2012 12:38:26 PM

DAMAGE SEE REMARKS

Ticket : 1208310816 Date: 08/31/2012 Time: 09:54 Oper: CSCOTT Chan:001

State: IN Cnty: HAMILTON Twp: ADAMS  
 Cityname: SHERIDAN Inside: Y Near: N  
 Subdivision: MAPLE RUN

Address :  
 Street : MAPLE RUN DR  
 Cross 1 : IN RT 47 Within 1/4 mile: Y  
 Location: FROM THE INTERSECTION PLEASE LOCATE BOTH SIDES OF MAPLE RUN DRIVE  
 HEADING SOUTH FOR 300 FEET-CONTACT JIM VERBOSKY WITH ANY QUESTIONS AT 317 714  
 2891  
 \*\*\*Boring Where = UNDER MAPLE RUN DRIVE 5 FEET DEEP  
 :  
 Grids : 4007B8613B 4007A8613B

Work type : SEWER AND WATER LINE INSTALLATION  
 Done for : WESTPORT HOMES  
 Start date: 08/31/2012 Time: 09:54 Hours notice: 0/000 Priority: EMER  
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: Y  
 Duration : 2 WEEKS Depth: 10 FEET

Company : HARVEY CONSTRUCTION Type: CONT  
 Co addr : 9125 EAST 146TH STREET  
 City : NOBLESVILLE State: IN Zip: 46060  
 Caller : MATT WILSON Phone: (317)773-7302  
 Contact : MERLIN WAGLER - CELL Phone:  
 BestTime:  
 Mobile : (317)714-0188  
 Fax : (317)773-7565  
 Email : MATT@HARVEYCONST.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 A VECTREN GAS LINE WAS CUT ON THE WEST SIDE OF MAPLE RUN DRIVE - GAS LINE IS  
 BLOWING - CALLER UNSURE IF YOU CAN HEAR OR SMELL GAS BUT CREW HAS REPORTED TO  
 HIM THAT THE GAS IS BLOWING - CALLER IS UNABLE TO DESCRIBE THE LINE - CREW IS ON  
 SITE - CALLER HAS NOTIFIED 911 - CALLER HAS BEEN ADVISED TO NOTIFY VECTREN -  
 PREVIOUS TICKET NUMBER 1208231192 - THANK YOU  
 Will you be white-lining the dig site area? YES  
 :

Submitted date: 08/31/2012 Time: 09:54  
 Members: ID0002 ID0103 ID0660 ID1370 ID5117 ID5293 ID8000 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
CABLE DIRECT / LONGVIEW COMMUNICATIONS	CABLE TV
COMCAST NORTHEAST (NOBLESVILLE)	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FIBERTECH	FIBER OPTIC
FRONTIER	TELEPHONE
SHERIDAN WATER & SEWER UTILITIES, TOWN OF	
VECTREN - NOBLESVILLE #1	GAS

[View Map](#)

[Close Map](#)

# Service Order Status

Thursday, September 13, 2012

**Enter Service Order Number:**

5354381



Clear Form

Refresh Data

**Banner Instance:**  CS03PROD  CS01PROD  CS02PROD

**Order Number:** N5354381

**Order Type:** INVE

**Order Status:** Completed

**Customer:** 009999999 - OWNER UNKNOWN

**Prem:** 5723847 - IN 47 & MAPLE RUN DR

**Technician:** 5417 - Houpt, Steve

**Order Dates and Times**

**Need Date:** 8/31/2012 11:22:00 AM  
**Time Created:** 8/31/2012 10:09:58 AM  
**Time Dispatched:** 8/31/2012 10:09:58 AM  
**Time In Route:** 8/31/2012 10:12:18 AM  
**Time On-Site:** 8/31/2012 10:32:12 AM  
**Tech Complete:** 8/31/2012 12:36:49 PM  
**Time Closed:** 8/31/2012 12:36:49 PM

**Events Performed/Completion Code**

IVEG - CMP

**Meter Information**

**Current ReadStatus**

**Old Meter:**

**New Meter:**

**Completion Notes**

LKOT/CONTRACTOR CUT 2 INCH PL MAIN/CREW WILL REPAIR/100 FT SOUTH OF RT 47 ON MAPLE RUN DR/MADE SAFE AT 1235PM

**Request Notes**

8/31/12- PER MATT WILSON/ OFF# 317-773-7302/ HIT/ BLOW MAIN- 1/4 MI FROM HSE- NO GAS ENTER INSIDE/ HIT W/ EXC INSTALL WATER LINE/ IN MAPLE RUN SUB/ HARVEY CONST/ MERLIN WAGLER ON SITE- 317-714-0188/ DAM# 12018310816/ #1208231192.

**MDSI Event Dates and Times**

Event	Date/Time	User
AsnAssignmentManualAck_evt	8/31/2012 10:12:14 AM	Houpt, Steve
AsnAssignmentEnRoute_evt	8/31/2012 10:12:18 AM	Houpt, Steve
AsnAssignmentOnSite_evt	8/31/2012 10:32:12 AM	Houpt, Steve
OrdOrderComplete_evt	8/31/2012 12:36:49 PM	Houpt, Steve

NOTE:The Reporting database replicates in near real-time; it has been approximately 1 minute(s) since the last transaction replicated.

# Service Order Status

Wednesday, September 12, 2012

**Enter Service Order Number:**

5354381



Clear Form

Refresh Data

**Banner Instance:**  CS03PROD  CS01PROD  CS02PROD  
**Order Number:** N5354381  
**Order Type:** INVE  
**Order Status:** Completed

**Customer:** 009999999 - OWNER UNKNOWN  
**Prem:** 5723847 - IN 47 & MAPLE RUN DR

**Technician:** 5417 - Houpt, Steve

**Order Dates and Times**

**Need Date:** 8/31/2012 11:22:00 AM  
**Time Created:** 8/31/2012 10:09:58 AM  
**Time Dispatched:** 8/31/2012 10:09:58 AM  
**Time In Route:** 8/31/2012 10:12:18 AM  
**Time On-Site:** 8/31/2012 10:32:12 AM  
**Tech Complete:** 8/31/2012 12:36:49 PM  
**Time Closed:** 8/31/2012 12:36:49 PM

**Events Performed/Completion Code**

IVEG - CMP

**Meter Information**

**Current ReadStatus**

**Old Meter:**  
**New Meter:**

**Completion Notes**

LKOT/CONTRACTOR CUT 2 INCH PL MAIN/CREW WILL REPAIR/100 FT SOUTH OF RT 47 ON MAPLE RUN DR/MADE SAFE AT 1235PM

**Request Notes**

8/31/12- PER MATT WILSON/ OFF# 317-773-7302/ HIT/ BLOW MAIN- 1/4 MI FROM HSE- NO GAS ENTER INSIDE/ HIT W/ EXC INSTALL WATER LINE/ IN MAPLE RUN SUB/ HARVEY CONST/ MERLIN WAGLER ON SITE- 317-714-0188/ DAM# 12018310816/ #1208231192.

**MDSI Event Dates and Times**

Event	Date/Time	User
AsnAssignmentManualAck_evt	8/31/2012 10:12:14 AM	Houpt, Steve
AsnAssignmentEnRoute_evt	8/31/2012 10:12:18 AM	Houpt, Steve
AsnAssignmentOnSite_evt	8/31/2012 10:32:12 AM	Houpt, Steve
OrdOrderComplete_evt	8/31/2012 12:36:49 PM	Houpt, Steve

NOTE:The Reporting database replicates in near real-time; it has been approximately 1 minute(s) since the last transaction replicated.