



Work Order	NA		Thursday, November 7, 2024			
Project Name	LoraLinda-Basin Maint					
Type	Maintenance -Structures					
<b>Manpower</b>	<b>TD/L</b>	<b>Operator</b>	<b>Light Operator</b>	<b>Working Total</b>		
Number of Employees	2	0	0			
Hours Worked	6	0	0			
Subtotal	\$ 255.60	\$ -	\$ -			
Total Including Fringe	\$ 311.7042	\$ -	\$ -	\$ 311.70		
<b>Equipment</b>	<b>Dump Truck</b>	<b>Backhoe</b>	<b>None</b>			
Number of Equipment	1	0	0			
Equipment Hours	6	0	0			
Total	\$ 394.50	\$ -	\$ -	\$ 394.50		
<b>Supervisor</b>	<b>Superintendent</b>	<b>Crew Leader</b>	<b>Crew Leader</b>			
Hours Worked	1	1	0			
Subtotal	42.09	28.05	0			
Total	\$ 51.33	\$ 34.21	\$ -	\$ 85.54		
<b>Equipment</b>	<b>Pick Up</b>	<b>Pick Up</b>	<b>None</b>			
Number of Equipment	1	1	0			
Equipment Hours	1	1	0			
Total	\$ 20.57	\$ 20.57	\$ -	\$ 41.14		
Total				\$ 832.88		
<b>Material</b>						
<b>Invoice Number(s)</b>						
Administrative	Administrative					
<b>Administrative Staff</b>	<b>Administrative</b>	<b>Director Operations</b>	<b>Engineer</b>	<b>Engineer In Training</b>	<b>Planning Tech</b>	<b>Working Total</b>
Hours Worked	1	0	0	0	0	
Subtotal	22.43	0	0	0	0	
Total with Fringe	\$ 27.35	\$ -	\$ -	\$ -	\$ -	\$ 27.35
<b>Equipment</b>	<b>None</b>	<b>None</b>	<b>None</b>	<b>None</b>	<b>None</b>	
Number of Equipment	0	0	0	0	0	
Equipment Hours	0	0	0	0	0	
Total	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -
Total						\$ 27.35

Complete through 11/07/2024